

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD State of New Mexico
Energy Minerals and Natural Resources
AUG 20 2014
RECEIVED Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011
Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company CHEVRON U.S.A Inc.	Contact: Josie DeLeon
Address 56 Texas Camp Road, Lovington, NM 88260	Telephone No. Office: 575-396-4414 ext 222 Cellular: 432-425-1528
Facility Name Vacuum Glorietta West Unit #85	Facility Type Production Well

Surface Owner State of New Mexico	Mineral Owner State of New Mexico	API No. 3002531129
-----------------------------------	-----------------------------------	--------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	6	18.0S	35.0E					Lea

Latitude 32.782150° Longitude -103.496157°

NATURE OF RELEASE

Type of Release Produced Water Spill; oil	Volume of Release 17.7 BW and .037 BO	Volume Recovered 3 BW
Source of Release Flowline leak due to integrity of line	Date and Hour of Occurrence 06/10/12 10:45	Date and Hour of Discovery 06/10/12 10:45
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mr. Leking via voicemail	
By Whom? Nick Moschetti	Date and Hour 06/10/12 10:45	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
NA

Describe Cause of Problem and Remedial Action Taken.*
Flowline Leak due to integrity of line

Describe Area Affected and Cleanup Action Taken.*
On discovery vacuum truck contacted and vacuumed up the standing fluids which were sent to disposal. Next steps are for the visually contaminated soil to be excavated up to 2 feet and sent off for disposal

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Josie DeLeon	Approved by Environmental Specialist:	
Title: Safety Specialist	Approval Date: 8-20-14	Expiration Date: 10-22-14
E-mail Address: jdx@chevron.com	Conditions of Approval: <i>Site specific regime submit final code 2 10-22-14</i>	Attached <input type="checkbox"/>
Date: 06/20/12 Phone: 432-425-1528		IRP-3265 <i>09710 4323 N701423 256144 P701423 256238</i>

* Attach Additional Sheets If Necessary

AUG 21 2014