

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
100 Rio Brazos Road, Aztec, NM 87410
District IV
20 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	COG OPERATING LLC	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Hoosier 22 State #002	Facility Type	Tank Battery

Surface Owner State	Mineral Owner	Lease No. (API#) 30-025-40876
---------------------	---------------	-------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	22	17S	35E					Lea

Latitude 32.82495 Longitude 103.43979

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 35bbls	Volume Recovered 30bbls
Source of Release Water tank	Date and Hour of Occurrence 04-06-2014	Date and Hour of Discovery 04-06-2014 12:00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoffery R. Leking - NMOCD	
By Whom? Michelle Mullins	Date and Hour 04-07-2014 07:23am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*


A valve on the water tank was unable to seal due to trash in the valve. We replaced the valve and checked for a good seal.

Describe Area Affected and Cleanup Action Taken.*

Initially 35bbls of produced water were released. We were able to recover 30bbls of produced water with a vacuum truck. All free fluids have been recovered. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by District Supervisor:	
Printed Name: Robert Grubbs Jr.	Approval Date:	Expiration Date:
Title: Senior Environmental Coordinator	Conditions of Approval:	
F-mail Address: rgrubbs@concho.com	Attached <input type="checkbox"/>	
Date: 04-22-2014 Phone: 432-661-6601		

* Attach Additional Sheets If Necessary