

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD

Form C-141
Revised August 8, 2011

AUG 26 2014 appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Devon Energy Production	Contact Kenny Kidd; Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 575-513-8545
Facility Name Harrod No. 1	Facility Type Gas Well
Surface Owner Private	Mineral Owner State
API No. 30-025-34535	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	9	16S	35E	1980	S	1870	E	Lea

Latitude: 32.93473903

Longitude: -103.459747851

NATURE OF RELEASE

Type of Release Spill	Volume of Release 130BBLS	Volume Recovered 0
Source of Release Broken gasket on man-way plate	Date and Hour of Occurrence 8.24.14 3:31PM	Date and Hour of Discovery 8.24.14 3:31 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM; Jim Amos & OCD Tomas Oberding	
By Whom? Assistant Foreman; Matthew Nettles	Date and Hour 8.25.14 @ 4:00 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

Broken gasket on the man- way plate. Gasket will be replaced once the NORM and Benzene levels are gathered and a safety plan is in place for the work to be performed safely.

Describe Area Affected and Cleanup Action Taken.*

The area affected was 24' x 21'. Spill occurred at the north oil tank. The condensate spilled into lined containment; however the condition of the liner will be inspected. Talon LPE will be inspecting the liner, assessing the spill and generating a plan for cleanup.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sandra Farley</i>	OIL CONSERVATION DIVISION	
Printed Name: Sandra Farley	<i>[Signature]</i> Approved by Environmental Specialist:	
Title: Field Admin Support	Approval Date: 8-26-14	Expiration Date: 10-27-14
E-mail Address: Sandy.Farley@dvn.com	Conditions of Approval: <i>Site specific report</i>	Attached <input type="checkbox"/>
Date: 8.26.14 Phone: 575.746.5587	<i>Dehute & route area on NMOCD grids. submit final C-141 by 10-27-14</i>	<i>LRP-3271</i> <i>og rid 6137</i> <i>N701423 838305</i> <i>P701423 83850</i>

* Attach Additional Sheets If Necessary

AUG 27 2014