

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011  
Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	Dry Lake 28 State #1	Facility Type	Production
Surface Owner	State	Mineral Owner	API No. 30-025-37551

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	28	21S	35E	660	North	1980	West	Lea County, NM

Latitude N 32.45492° Longitude W 103.37438°

**NATURE OF RELEASE**


Type of Release	Oil and produced water	Volume of Release	70 bbls oil, 80 bbls produced water	Volume Recovered	30 bbls oil, 50 bbls produced water
Source of Release	Tank integrity	Date and Hour of Occurrence	08/19/2011	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Geoffrey Leking, NMOCD		
By Whom?	CJ Summers	Date and Hour	08/19/2011		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
Hole developed in bottom area of tank due to possible tank integrity issue from previous lightning strike. A Vac Truck was dispatched to the area and recovered all free standing fluids.

Describe Area Affected and Cleanup Action Taken.\*  
The area affected is approximately 40' x 20' on location just East of the tanks. Remediation was completed in accordance with the remediation plan approved by Geoffrey Leking of NMOCD via email on 09/24/2012.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:				<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	Chancey Summers			Approved by Environmental Specialist:	
Title:	HES Advisor			Approval Date:	8-26-14
E-mail Address:	Chancey.Summers@oxy.com			Expiration Date:	
Date:	8-21-14			Conditions of Approval:	
Phone:	(575) 397-8216			Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

1RP-3274  
OG 112 16696  
NT 1423 851890  
PT 0423 852074  
AUG 27 2014