


District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

NAB1424134595 OPERATOR Initial Report Final Report
 Name of Company *Linn Operating Inc. 269324* Contact Brian Wall
 Address 2130 W Bender Blvd Hobbs, NM 88240 Telephone No. 575-738-1739
 Facility Name JL Keel B #10 Facility Type Injection

Surface Owner Federal Mineral Owner API No. 30-015-05110

LOCATION OF RELEASE

Unit Letter B	Section 08	Township 17S	Range 31E	Feet from the 660	North/South Line North	Feet from the 1980	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.85446 Longitude -103.88899

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 103 bbls	Volume Recovered 0
Source of Release Fiberglass pipeline	Date and Hour of Occurrence 08/26/2014	Date and Hour of Discovery 08/26/2014 10:30am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* Received call from foreman that diversified crew had hit one of the lines while getting samples for clean up by the Keel B #10 drove up to location to see what they had hit and crew was actually getting samples right on top of the ROW immediately identified line that was hit which was 8" fiber glass transfer line that runs East & West along with 3 other injection lines & goes from Keel B & Keel A Battery to water station s/i valves on both ends of line, went back to where they strike line and noticed that line had already been marked for crew to get samples.

Describe Area Affected and Cleanup Action Taken.* Leak is approx 10' x 60' on N side of the road leak continued going south of road approx 2' x 800' down the arroyo.
 Directions to site: FROM US-82 AND NM-529, W ON US-82 to CR 221 GO 1.4 miles ON CR221 R (N) GO 0.5MI. Road curves E 0.6MI. TRN N 0.4MI. TRN E 0.5 to inj well on N side go 500 ft east to spill

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Brian Wall</i>	OIL CONSERVATION DIVISION	
Printed Name: Brian Wall	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Construction Foreman II	Approval Date: <i>8/29/14</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>bwall@linnenergy.com</i>	Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION	Attached <input type="checkbox"/>
Date: 08/28/2014 Phone: 806-367-0645		

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:

9/29/14

2RP-2401

Bratcher, Mike, EMNRD

From: McCracken, Theresa <TMcCracken@linnenergy.com>
Sent: Thursday, August 28, 2014 11:41 AM
To: jlrobertson@blm.gov; Bratcher, Mike, EMNRD
Cc: Moreno, Laura; Butters, Thomas; Gonzales, EL; Wall, Fred; Hickert, Aaron; mpatterson@diversifiedfsi.com; Natalie Gladden (ngladden@diversifiedfsi.com); rpons@diversifiedfsi.com; smcghee@diversifiedfsi.com
Subject: Linn- JL Keel B 10 8-26-14
Attachments: Keel B 10 8-26-14.pdf; photo 2.JPG; photo 3.JPG
Importance: High

Please find attached the initial C-141 for the above referenced location.

Thank you,



Theresa McCracken

Field Administrator

LINN Energy, LLC

2130 W Bender

Hobbs, NM 88240

T: 575-738-1739 / F: 575-738-1740

tmccracken@linnenergy.com

This electronic message, together with any attachments, contains information from LINN Energy that may be confidential and intended solely for the use of the addressee only. If you are not the intended recipient, please note that any disclosure, dissemination, distribution or copying of this message, or any attachment, is strictly prohibited. Also, please notify the original sender by return e-mail and delete the message, along with any attachments, from your computer. Finally, the recipient should check this email and any attachments for the presence of viruses. The organization accepts no liability for any damage caused by any virus transmitted by this email.