

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NABI424041822 **OPERATOR** Initial Report Final Report

Name of Company: BOPCO, L.P. <i>260737</i>	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: JRU-35 The flow line spill was 1475 ft. southwest of the well pad.	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-31167
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	I	23S	30E					Eddy

Latitude N 32.337484 Longitude W 103.831995

NATURE OF RELEASE

Type of Release: Crude oil and produced water	Volume of Release: 3 bbls oil and 7 bbls water	Volume Recovered: None
Source of Release: 3" poly flow line	Date and Hour of Occurrence: 8/14/14 at 8:30 a.m.	Date and Hour of Discovery: 8/14/14 at 8:30 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

NM OIL CONSERVATION

ARTESIA DISTRICT

SEP 02 2014

RECEIVED

Describe Cause of Problem and Remedial Action Taken.*
The 3" poly line was cut by a road grader operated by MJ Services. The well was shut in and the damaged section of pipe was cut out and replaced.

Describe Area Affected and Cleanup Action Taken.*
The spill impacted approximately 3500 sq.ft. of caliche lease road and misted approximately 400 sq.ft. of pasture. The saturated soil was scraped up and stockpiled at the Hudson Federal Battery pending removal. Clean caliche was used to re-cover the exposed line. The spill will be cleaned up in accordance to the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Waste Management and Remediation Specialist	Approval Date: <i>9/18/2014</i>	Expiration Date: <i>NIA</i>
E-mail Address: <i>tasavoie@basspet.com</i>	Conditions of Approval:	
Date: 9/2/14 Phone: 432-556-8730	Remediation per OCD Rule & Guidelines. Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO LATER THAN: *10/31/2014*

2RP-2467



JRU-112H

JRU-33

JRU-35

Spill 8-14-14

on 1 Fed:SWD

JRU-36

JRU-10

009