

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1425128333

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company Devon Energy	<i>10137</i>	Contact: Martin Jimenez	
Address PO Box 250 Artesia, NM 88211		Telephone No.: 575-748-0197	
Facility Name Antares 23 Federal #13H		Facility Type Oil Well	
Surface Owner Federal	Mineral Owner	API No. 30-015-42076	

LOCATION OF RELEASE

Unit Letter E	Section 23	Township 19S	Range 31E	Feet from the 2400'	North/South Line North	Feet from the 190'	East/West Line West	County Eddy
-------------------------	----------------------	------------------------	---------------------	-------------------------------	----------------------------------	------------------------------	-------------------------------	-----------------------

Latitude: **32.6466399 N** Longitude: **103.8479293 W**

NATURE OF RELEASE

Type of Release: Hydrochloric Acid	Volume of Release 70 bbls	Volume Recovered -0- bbls
Source of Release: Hole in Frac Tank	Date and Hour of Occurrence: 8/25/2014 @ 9:00 am	Date and Hour of Discovery: 8/25/2014 @ 9:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos BLM & Mike Bratcher NMOCD	
By Whom? Jason Lipscomb	Date and Hour: 8/25/2014 @ approx 2:30 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* <input type="checkbox"/> Devon Energy was completing the well. When personnel arrived on the location a frac tank containing hydrochloric acid was found to be leaking. 70 barrels of frac acid was release and flowed under the tanks, with no fluids recovered. Baker Hughes treated the impacted area around the frac tanks with soda ash.		
Describe Area Affected and Cleanup Action Taken.* <input type="checkbox"/> The affected area measured approximately 10'x25' which remained on the location and did not impact adjacent pasture lands. Talon/LPE was called to remediate this incident. The impacted area will be scraped approximately 0.25-foot deep and disposed of at a NMOCD approved facility. The excavated area will be subsequently tested for pH. Upon acceptable results, the NMOCD and BLM will be petitioned for approval to backfill and reconstruct the location.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>Denise Menoud</i>	OIL CONSERVATION DIVISION	
Printed Name: Denise Menoud	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Admin Field Support 4 / Completions	Approval Date: 9/8/14	Expiration Date: N/A
E-mail Address: Denise.Menoud@dvn.com	Conditions of Approval:	
Date: 9/4/2014 Phone: 575.746.5544	Remediation per OCD Rule & Guidelines.	

* Attach Additional Sheets If Necessary

**SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 10/8/14**

2RP-2473

**NM OIL CONSERVATION
ARTESIA DISTRICT**

SEP 05 2014

RECEIVED

Patterson, Heather, EMNRD

From: Harris, Jacqui <Jacqui.Harris@dvn.com>
Sent: Friday, September 05, 2014 10:45 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; jrobertson@blm.gov
Subject: Antares 23 Fed 13H
Attachments: Antares 23 Fed 13H C141 Talon 9_4_14.pdf

Please find the C-141 attached for the above well.

Mike & Heather,
Can you please confirm you received this email or give a confirmation #?

If you have questions or need anything further concerning this please contact me.

Thank you,

Jacqui Harris



Devon Energy Productions
6488 Seven Rivers Hwy
Artesia, NM 88210
(575)748-0191

Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.