

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nJMW 1400355171

OPERATOR

Initial Report Final Report

Name of Company <i>Enterprise Field Services LLC 1000347</i>	Contact <i>Jim Heap</i>
<i>PO Box 4324, Houston, TX 77252</i>	Telephone No. <i>432-686-5404</i>
Facility Name <i>Pipeline ROW, Baldrige Canyon Lateral</i>	Facility Type: <i>Gas Gathering Pipeline</i>
Surface Owner <i>State of NM</i>	Mineral Owner <i>NA</i>
	Lease No. <i>NA</i>

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	<i>12</i>	<i>24S</i>	<i>24E</i>					<i>Eddy</i>

Latitude: *N 32.250350* Longitude: *W -104.470564*

NATURE OF RELEASE

Type of Release <i>Natural Gas</i>	Volume of Release <i>1,521 MCF</i>	Volume Recovered <i>0</i>
Source of Release <i>Pipeline Leak, small hole in pipe-wall.</i>	Date and Hour of Occurrence <i>12/13/2013 18:00 MST</i>	Date and Hour of Discovery <i>12/13/2013 19:00 MST</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>Randy Dade, District 2</i>	
By Whom? <i>Jim Heap</i>	Date and Hour <i>12/14/2013 @ 10:00 MST</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Small hole in the pipe-wall; suspected corrosion fault. Loss volume includes blow-down loss for repair.

Describe Area Affected and Cleanup Action Taken.*
The line was isolated and prepared for repairs.

RECEIVED
DEC 23 2013
NMOCD ARTESIA

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION	
Printed Name: <i>Jon E. Fields</i>	Approved by District Supervisor: Signed By <i>[Signature]</i>	
Title: <i>Director, Field Environmental</i>	Approval Date: JAN 03 2014	Expiration Date:
E-mail Address: <i>jefields@eprod.com</i>	Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	Attached <input type="checkbox"/>
Date: <i>12-17-2013</i> Phone: <i>713-381-6684</i>	2RP-2138	

* Attach Additional Sheets If Necessary

fJMW 1333128849

Feb. 3, 2014


iJMW 1400355656



ENTERPRISE PRODUCTS PARTNERS L.P.
ENTERPRISE PRODUCTS HOLDINGS LLC
(General Partner)

ENTERPRISE PRODUCTS OPERATING LLC

December 17, 2013



7012 3460 0003 3115 9197
Return Receipt Requested

Mr. Mike Bratcher
New Mexico Oil Conservation Division
District 2 Office
811 South First Street
Artesia, New Mexico 88210

**RE: Form C-141 Report for Enterprise Field Services LLC
Natural Gas Release on Carlsbad Gathering Lines**

Mr. Bratcher

Enclosed, please find the requisite C-141 Form for the initial report of the Eddy County release of our Baldrige Canyon Lateral on 13DEC2013. At this time, only natural gas was determined to be released.

This report is sent pursuant to 29 (19.15.29) NMAC and as follow-up to a verbal notifications made to Randy Dade by phone on December 14, 2013. Final reports for these releases will be sent when repairs have been made and the extent of any liquids released can be determined. The Lease owner, State of New Mexico, has been notified.

If you have any questions or need more information, please contact Jim Heap by phone at 432-686-5404, by email at jkheap@eprod.com or me at 713-318-6684

Regards,

Jon E. Fields
Director, Field Environmental

/sjn
attachments