

HOBBS OCD

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
September 11 2014  
Generals and Natural Resources  
Oil Conservation Division  
RECEIVED  
200 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report  Final Report

Name of Company - EOG Resources	Contact - Zane Kurtz	
Address - 5509 Champions Drive, Midland, Texas 79703	Telephone No. 432-425-2023	
Facility Name - Madera Ridge 25 Fed #1	Facility Type - Oil Well	
Surface Owner	Mineral Owner	API No. 30-025-28533

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	25	24S	33E	1980'	South	660'	West	Lea

Latitude 32.1866 Longitude -103.5323

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 10 bbls	Volume Recovered 8 bbls
Source of Release - Fire Tube Leak	Date and Hour of Occurrence May 2014 Unknown hour	Date and Hour of Discovery May 2014 Unknown hour
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* A leak from a fire tube occurred from equipment malfunction and released produced water. The fire tube has since been repaired.		
Describe Area Affected and Cleanup Action Taken.* Approximately 10 bbls of produced water was released from equipment malfunction. 8 bbls were recovered and all fluids released stay within the pad site. The impacted area will be excavated, stockpiled, on poly-plastic, and transported to Sundance disposal facility. Clean material will be backfilled within the excavated area to normal grade.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Zane Kurtz	Approved by Environmental Specialist:	
Title: Sr. Safety and Environmental Rep., EOG Resources	Approval Date: 9-11-14	Expiration Date: 11-11-14
E-mail Address: Zane_Kurtz@eogresources.com	Conditions of Approval: Site Samples required	Attached <input type="checkbox"/>
Date: 09/11/2014 Phone: 432-425-2023	IRP-3316 Ogrid 7377 87014 25428176 87014 25428328	

\* Attach Additional Sheets If Necessary

Relevant & complete one on per NMOCD guide. Submit final C-141 by 11-11-14. SEP 11 2014