

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	COG OPERATING LLC	Contact	Robert McNeill
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Burch Keely Unit #232	Facility Type	Tank Battery
Surface Owner	Federal	Mineral Owner	
		Lease No. (API#)	30-015-27992

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	23	17S	29E					Eddy

Latitude 32.81382 Longitude 104.04572

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	80bbbls	Volume Recovered	75bbbls
Source of Release	Transfer filter pot	Date and Hour of Occurrence	02-22-2014	Date and Hour of Discovery	02-22-2014 05:15am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher - NMOCD		
By Whom?	Michelle Mullins	Date and Hour	02-24-2014 3:332pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

NM OIL CONSERVATION

If a Watercourse was Impacted, Describe Fully.*

ARTESIA DISTRICT
JUL 28 2014


Describe Cause of Problem and Remedial Action Taken.*

Valve was not completely closed witch caused the hose to pressure up enough to pop loose the connection on the bottom of the filter pot. Hose will be replaced and valve closed completely.

Describe Area Affected and Cleanup Action Taken.*

Initially 80bbbls of produced water were released. We were able to recover 75bbbls with a vacuum truck. All free fluids have been recovered Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD/BLM for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Lupe Carrasco	Approved by District Supervisor: 	
Title: Environmental Coordinator	Approval Date: 7/24/14	Expiration Date: NA
E-mail Address: gcarrasco@concho.com	Conditions of Approval: <i>Final</i>	Attached <input type="checkbox"/>
Date: 7/28/14	Phone: 575-748-6933	

* Attach Additional Sheets If Necessary

220-2220