

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION**  
ARTESIA DISTRICT Form C-141  
Revised August 8, 2011  
Submit 1 Copy to Appropriate District Office in accordance with 19.15.29 NMAC.

SEP 15 2014

RECEIVED

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

*NAB 143 592 6900*

Name of Company: COG Operating LLC <i>217955</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Momba 24 Federal Com #3	Facility Type: Battery
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-40946	

**LOCATION OF RELEASE**

Unit Letter B	Section 24	Township 26S	Range 28E	Feet from the 43	North/South Line North	Feet from the 2180	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	---------------------	---------------------------	-----------------------	------------------------	----------------

Latitude N32°02.102' Longitude W104°02.353'

**NATURE OF RELEASE**

Type of Release: Oil and Produced Water	Volume of Release: 3 bbls Oil; 250 bbls PW	Volume Recovered: 3 bbls Oil; 247 bbls PW
Source of Release: Water tank	Date and Hour of Occurrence: 9/14/2014 1:00 pm	Date and Hour of Discovery: 9/14/2014 1:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher -- NMOCD ; Jim Amos - BLM	
By Whom? Amanda Trujillo	Date and Hour: 9/15/2014 5:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
The nipple on the water tank load line broke causing the discharge of fluid. Repairs were made and the tank was put back into production.

Describe Area Affected and Cleanup Action Taken.\*  
The release occurred within a lined facility. Vacuum trucks were dispatched to recover standing fluid and dispose of at an NMOCD approved facility. Impacted gravel was excavated, the area was pressure washed and the gravel was replaced.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>A Trujillo</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Senior Environmental Coordinator	Approval Date: <i>9/16/14</i>	Expiration Date: <i>NA</i>
E-mail Address: <a href="mailto:atrujillo@concho.com">atrujillo@concho.com</a>	Conditions of Approval: <i>Final</i>	Attached <input type="checkbox"/>
Date: September 15, 2014	Phone: 575-748-6940	

\* Attach Additional Sheets If Necessary

*2RP-2486*

## **Patterson, Heather, EMNRD**

---

**From:** Amanda Trujillo <ATrujillo@concho.com>  
**Sent:** Monday, September 15, 2014 4:54 PM  
**To:** Bratcher, Mike, EMNRD; james\_amos@blm.gov  
**Cc:** Patterson, Heather, EMNRD; jlrobertson@blm.gov  
**Subject:** (Notification - C-141 Initial-Final) Momba 24 Federal Com #3 (30-015-40946)  
**Attachments:** 09-14-2014 Momba 24 Federal Com #3 (TB) Inital-Final.pdf

Mr. Bratcher/Mr. Amos,

COG Operating LLC is reporting a release at the **Momba 24 Federal Com #3 (30-015-40946)**.

Unit B Section 24 Township 26S Range 28E

The release occurred at 1:00 pm on 09/14/2014.

**Released:** 3 bbls Oil; 250 bbls PW

**Recovered:** 3 bbls Oil; 247 bbls PW

This release was caused by corroded nipple on the water tank. The release occurred in a lined facility. Attached is a C-141 Initial/Final for your consideration. If you have any additional questions please feel free to contact me.

Thank you,

### **Amanda Trujillo**

Senior Environmental Coordinator

COG Operating LLC

Cell: 505.350.1336

Office: 575.748.6930

[atrujillo@concho.com](mailto:atrujillo@concho.com)

2208 W. Main St.

Artesia , NM 88210



**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.