

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

SEP 15 2014

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Burgundy Oil and Gas of New Mexico	Contact: Ben Taylor
Address: 401 W Texas Suite 1003 Midland, TX 79701	Telephone No. 432-684-4033
Facility Name: Childress Road Leak	Facility Type: Gas Production

Surface Owner Federal	Mineral Owner Federal	API No. 30-025-64319 (nearest facility)
-----------------------	-----------------------	---

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from	East/West Line	County
	3	20S	36E					Lea

Latitude: 32.60033 Longitude -103.34065

NATURE OF RELEASE

Type of Release: Produced water/crude	Volume of Release unknown	Volume Recovered unknown
Source of Release: Flowline	Date and Hour of Occurrence	Date and Hour of Discovery

Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? DFSI Mike Burton SR Project Manager
--	---

By Whom? Ben Taylor	Date and Hour: 07/23/14 3:29
---------------------	------------------------------

Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.
---	---

If a Watercourse was Impacted, Describe Fully.*
NA

Describe Cause of Problem and Remedial Action Taken.* A rupture occurred in a Flow line located off of the Childress lease road.

Describe Area Affected and Cleanup Action Taken. This created an impact to pasture area measuring 2,657 sq. ft. DFSI was retained to remediate the site. Remediation efforts have been completed, and the pasture area restored to its natural state per BLM requirements.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Ben Taylor		OIL CONSERVATION DIVISION	
Printed Name: Ben Taylor		Approved by Environmental Specialist:	
Title: Field Foreman		Approval Date: 9-15-14	Expiration Date: _____
E-mail Address: btaylor.bogi@att.net		Conditions of Approval:	
Date: 08/05/14 Phone: 432-557-2684		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

SEP 16 2014

IRP- 3212
Og rid 3044
N7014 218 31023
O701421 85113F