

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company: <b>ConocoPhillips</b>	Contact: <b>Spencer Cluff</b>
Address: <b>29 Vacuum Complex Lane</b>	Telephone No. <b>575-391-3143</b>
Facility Name: <b>Santa Fe Battery</b>	Facility Type: <b>Heater Treater</b>
Surface Owner: <b>NMOCD</b>	Mineral Owner <b>NMOCD</b> API No. <b>30-025-32333</b>

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	31	17S	35E	435	South	1930	East	LEA

Latitude 32.7854367361682 Longitude - 103.494735819723

**NATURE OF RELEASE**


Type of Release: <b>Spill</b>	Volume of Release: <b>20 BBLs</b>	Volume Recovered: <b>10 BBLs</b>
Source of Release: <b>Heater Treater</b>	Date and Hour of Occurrence <b>09/11/14 4:00 am</b>	Date and Hour of Discovery <b>09/12/2014 7:3- am</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Tomáš Oberding</b>	
By Whom? <b>Spencer Cluff</b>	Date and Hour: <b>09/12/2014 7:10 am</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
On September 12th, 2014, in the early morning hours, at the Santa Fe 133 Battery, a release of oil and produced water occurred. The release originated from the test heater that fell over and was damaged during heavy thunderstorms. Operations was contacted by an offset operator and informed that the heater had fallen. The lease was shut in at the time of the incident. The affected area was 200 ft. X 200 ft. X 0.25 inches deep and resulted in 10 bbls oil and 10 bbls produced water, with 10 bbls recovered. The affected area will be remediated according to NMOCD guidelines.

Describe Area Affected and Cleanup Action Taken.\*  
The lease was shut in at the time of the incident.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

		<b>OIL CONSERVATION DIVISION</b>	
Signature: <i>Spencer A. Cluff</i>	 Approved by Environmental Specialist:		
Printed Name: Spencer Cluff			
Title: HSE Lead	Approval Date: <b>9-15-14</b>	Expiration Date: <b>11-15-14</b>	
E-mail Address: <b>spencer.a.cluff@conocophillips.com</b>	Conditions of Approval: <i>Site Super agreed Dolomite &amp; sandstone man as per NMOCD guide. Submit final</i>		Attached <input type="checkbox"/>
Date: 09/15/2014	Phone: 575-391-3143	<b>IRP-3321</b>	

\* Attach Additional Sheets If Necessary

C-141 by 11-15-14

SEP 16 2014 08:19 217817  
1701425 857071  
1701425 857207