

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

HOBBS OCD

Form C-141  
Revised August 8, 2011

SEP 16 2014

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Air Cobra 12 State #2H	Facility Type: Tank Battery

Surface Owner: State	Mineral Owner:	API No. 30-025-40035
----------------------	----------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	12	19S	34E	510	North	1980	East	Lea

Latitude 32'40.864' Longitude W103'30.683'

**NATURE OF RELEASE**


Type of Release: Oil	Volume of Release: 70 bbls	Volume Recovered: 68 bbls
Source of Release: Fitting on flow line in battery	Date and Hour of Occurrence: 9-11-2014 10:28 am	Date and Hour of Discovery: 9-11-2014 10:28 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
While doing routine maintenance on a separator a roustabout crew did not properly plug a 2" line. This line was the source point for the release. Crews made corrections and battery was put back online.

Describe Area Affected and Cleanup Action Taken.\*  
The release occurred within a lined facility. Vacuum trucks were dispatched to recover any free standing fluids. The battery was steam cleaned and gravel replaced.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: 9-16-14	Expiration Date: _____
E-mail Address: atrujillo@concho.com	Conditions of Approval: <u>Lined Facility</u>	Attached <input type="checkbox"/>
Date: September 15, 2014 Phone: 575-748-6940		IRP-3322

\* Attach Additional Sheets If Necessary

Ogria 229137  
N701425926117  
P710 1425 926275

SEP 16 2014