

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD

Form C-141
Revised October 10, 2003

SEP 16 2014

Submit to appropriate District Office in accordance with 19.15.29 NMAC

RECEIVED

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Linn Operating	Contact: Brian Wall
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: Caprock Maljamar Unit #285	Facility Type: Oil Producer

Surface Owner: Federal	Mineral Owner:	API No.: 30-025-34257
------------------------	----------------	-----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	33	17S	33E	330	North	2310	East	Lea

Latitude: 32.7974215844725 Longitude: -103.667119626025

NATURE OF RELEASE

Type of Release: Produced Water / Oil	Volume of Release: 10 gal / 1 gal	Volume Recovered: 0 / 0
Source of Release: Poly pipeline	Date and Hour of Occurrence: 07/28/2014	Date and Hour of Discovery: 07/28/2014 1:00pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeff Robertson - BLM	
By Whom? Brian Wall	Date and Hour 07/29/2014	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: At appx 1:00p.m. on 7/28/14 I received a phone call that I had a flow line leak at the CMU #285. I arrived to location to find that the poly pipe flow line was misting out of the weld. It released appx 10 gals of produced water and appx 1 gal of oil. Where line was leaking there is an old leak. The size of area affected is appx 10' long and 8' wide.

Describe Area Affected and Cleanup Action Taken.* : The size of area affected is appx 10' long and 8' wide. West of the wellhead about 60 yards, 20 yards off of location, Northwest corner.
Directions to site: From Maljamar go South on Hwy 126 6/10 of a mile turn on Hwy 125 (Mescalero Rd) go 5.7 miles then turn right, then go 2/10 mile to location on your left.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Brian Wall</i>	OIL CONSERVATION DIVISION	
Printed Name: Brian Wall	Approved by District Supervisor: <i>Brian Wall</i>	
Title: Construction Foreman II	Approval Date: 9-18-14	Expiration Date: 11-18-14
E-mail Address: bwall@linenergy.com	Conditions of Approval: <i>Site Sample required</i>	Attached <input type="checkbox"/> <i>IRP - 3325</i>
Date: 07/29/2014 Phone: 806-367-0645	<i>delimited redacted area upon NMOCD guidance. Submit final C-141 by 11-18-14</i>	

* Attach Additional Sheets If Necessary

SEP 16 2014

*09-18-14 269324
NTO 1425 937487
PTO 1425 937660*