

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

SEP 16 2014
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1425953776 OPERATOR Initial Report Final Report

Name of Company: BOPCO, L.P. <i>2100737</i>	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU 420 Tank Battery	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-39795
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	28	25S	31E	700	South	1300	East	Eddy

Latitude N 32.096093 Longitude W 103.778400

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 135 bbls	Volume Recovered: None
Source of Release: 1/2" valve on the free water knockout	Date and Hour of Occurrence: 9/9/14 time unknown	Date and Hour of Discovery: 9/9/14 at approximately 12:50 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD emergency #104 and BLM	
By Whom? Tony Savoie	Date and Hour: 9/10/14 at approximately 12:30 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* It appeared that a cow kicked the valve handle on the 1/2" valve to the open position. The valve was shut and handle removed. The area will be completely fenced off after the remediation is completed.		
Describe Area Affected and Cleanup Action Taken.* All of the fluid soaked into the ground. The spill affected approximately 15,400 sq.ft. around the process equipment earthen containment and well pad area. The release impacted an area previously reported; reference 2RP-2250. The spill area will be cleaned up in accordance to the NMOCD and BLM remediation guidelines		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by Environmental Specialist: <i>H. Huber</i>	
Title: Waste Management and Remediation Specialist	Approval Date: <i>9/16/14</i>	Expiration Date: <i>NA</i>
E-mail Address: <i>tasavoie@basspet.com</i>	Attached <input type="checkbox"/>	
Date: <i>9/16/14</i> Phone: 432-556-8730	Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <i>10/16/14</i>	

* Attach Additional Sheets If Necessary

2RP-2487

9/10/2014 10 am

PLU-420-9-10-14 AM

Point Of Release

