

NM OIL CONSERVATION

ARTESIA DISTRICT

SEP 17 2014

Form C-141
Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
Please copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1426052450

OPERATOR

Initial Report Final Report

Name of Company Yates Petroleum Corporation <i>25575</i>	Contact Amber Cannon
Address 104 S. 4 th Street	Telephone No. 575-748-4111
Facility Name Martha AIK Federal #6	Facility Type Production Flow Line

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-26960
--------------------------	--------------------------	-------------------------

LOCATION OF RELEASE

Unit Letter A	Section 11	Township 22S	Range 31E	Feet from the 660	North/South Line North	Feet from the 330	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.41137 Longitude 103.74056

NATURE OF RELEASE

Type of Release Crude Oil & Produced Water	Volume of Release 10 B/O & 10 B/PW	Volume Recovered 0 B/O & 0 B/PW
Source of Release Flow line	Date and Hour of Occurrence 8/9/2014; AM	Date and Hour of Discovery 8/9/2014; AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully. N/A

Describe Cause of Problem and Remedial Action Taken.

There was a leak in the flow line, causing the release. Vacuum truck(s) and roustabout crew called.

Describe Area Affected and Cleanup Action Taken.

An approximate area of 25' X 25'. The impacted area was near the production pad for the Martha AIK Federal #13. The line was repaired. Vertical and horizontal delineation samples have been taken and analysis will be run for TPH & BTEX (chlorides for documentation). If initial analytical results for TPH & BTEX are under RRAL's (site ranking is 0) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL's a work plan will be submitted to the OCD. **Depth to Ground Water: >100' (approximately 100-125', Section 11, T22S-R31E, per Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Amber Cannon</i>	Approved by Environmental Specialist: <i>[Signature]</i>
Printed Name: Amber Cannon	Approval Date: <i>9/17/14</i> Expiration Date: <i>NA</i>
Title: NM Environmental Regulatory Agent	
E-mail Address: ACannon@yatespetroleum.com	
Date: August 13, 2014 Phone: 575-748-4111	Conditions of Approval: Remediation per OCD Rule & Guidelines. Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 10/17/14

2 RP-2491

Patterson, Heather, EMNRD

From: Bob Asher <BobA@yatespetroleum.com>
Sent: Sunday, September 14, 2014 7:57 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Dade, Randy, EMNRD; dwhitloc@blm.gov; jamos@blm.gov
Cc: Amber Cannon; Chase Settle; Katie Parker; Manuel Gonzalez; Tanna Adams
Subject: Release Notification (Martha AIK Federal #14)

Yates Petroleum Corporation is reporting a release at the following location (9/13/2014; 10:00 AM).

Martha AIK Federal #14
30-015-37556
Section 11, T22S-R31E
430 FSL & 178 FEL
Eddy County, New Mexico

Released: 60 B/O; Recovered: Unknown at this time.

Cause of release was from a stuffing box blow out. Vacuum truck(s) called and a backhoe called. A Form C-141 with full detailed information will be submitted.

Thank you.

Robert Asher
NM Environmental Regulatory Supervisor
Yates Petroleum Corporation
105 S. 4th Street
Artesia, NM 88210
575-748-4217 (Office)
575-365-4021 (Cell)

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
