

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION** Form C-141  
ARTESIA DISTRICT Revised August 8, 2011  
AUG 28 2014  
Submit 1 copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

*NAB1420153067*

Name of Company <b>ENERGYQUEST</b> <i>305911</i>		OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address <b>4526 RESEARCH FOREST DRIVE, SUITE 200 THE WOODLANDS, TX 77381</b>		Contact <b>Larry Davis</b>		
Facility Name <b>GRAYBURG JACKSON</b>		Telephone No. <b>281-651-5201</b>		
		Facility Type <b>OIL</b>		

Surface Owner <b>BLM</b>	Mineral Owner	API No. <i>30-015-20250</i>
--------------------------	---------------	-----------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
		17S	30E					

Latitude *32-47-11* north Longitude *104-1-37* west

*[32-47-34N, 104-3-35W]*

**NATURE OF RELEASE**

Type of Release <b>OIL</b>	Volume of Release <b>&gt;2 bbls</b>	Volume Recovered <b>0</b>
Source of Release <b>DAMAGE TO FLOWLINES - THREE (3) LOCATIONS</b>	Date and Hour of Occurrence <b>21-23 AUG 2014, EXACT TIME UNKNOWN</b>	Date and Hour of Discovery <b>23 AUG 2014, 1500 HOURS</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>BLM via voice mail</b>	
By Whom? <b>GREG MCWILLIAMS, ENERGYQUEST</b>	Date and Hour <b>23 AUGUST 2014, 1500 HOURS</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

THREE (3) LOCATIONS OF DAMAGED FLOWLINES CAUSED BY VEHICLES USED BY DEAN'S ELECTRIC WHILE WORKING ON POWER LINES. FLOWLINES LOCATED ALONG THE SIDE OF THE FIELD ROAD; ONLY ONE PUMP WAS ACTIVE AT THE TIME, AND IT WAS SHUT-IN UPON DISCOVERY. SEE ATTACHED DESCRIPTION AND PHOTOS.

Describe Area Affected and Cleanup Action Taken.\*

SURFACE SAND AND DAMAGED VEGETATION WERE REMOVED FROM THE RELEASE SITES VIA BACKHOE. POWER WILL NOT BE RESTORED UNTIL ALL DAMAGED FLOW LINES HAVE BEEN REPAIRED OR REPLACED AS NECESSARY.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Larry Davis</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>LARRY DAVIS</b>	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: <b>ENVIRONMENTAL QUALITY MANAGER</b>	Approval Date: <i>9/18/14</i>	Expiration Date: <i>NA</i>
E-mail Address: <b>larry.davis@energyquest.us</b>	Attached <input type="checkbox"/>	
Date: <i>28 Aug 2014</i> Phone: <b>281-651-5201</b>	<b>Conditions of Approval:</b> Remediation per OCD Rule & Guidelines.	

SUBMIT REMEDIATION PROPOSAL NO  
LATER THAN: *10/18/14*

\* Attach Additional Sheets If Necessary

*2RP 2492*