

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

HOBBS OGD

SEP 22 2014

RECEIVED

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	Oxy Permian Ltd.	Contact	CJ Summers
Address	1017 W. Stanolind Rd, Hobbs, NM	Telephone No.	(575) 397-8216
Facility Name	Federal 27 #1 CTB	Facility Type	Gathering
Surface Owner	BLM	Mineral Owner	
		API No.	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	27	22S	32E					Lea

Latitude N 32.35611° Longitude W 103.66351°

**NATURE OF RELEASE**



Type of Release	Oil	Volume of Release	40 bbls oil	Volume Recovered	35 bbls
Source of Release	Dump valve malfunction on the heater treater caused the tanks to overflow	Date and Hour of Occurrence	04/14/14	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Geoffrey Leking-NMOCD; Jennifer Van Curen-BLM		
By Whom?	Kathy Purvis, BBC International	Date and Hour	04/14/14 @ 3:50 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
A dump valve malfunctioned on the heater treater causing the tanks to overflow and spill 40 bbls of oil onto the ground. A vacuum truck recovered 35 bbls of oil and the dump valve was repaired or replaced.

Describe Area Affected and Cleanup Action Taken.\*  
The affected area is approximately 10' x 60' on and off location. Remediation will be performed in accordance with a plan approved by NMOCD and BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	Chancey Summers	Approved by District Supervisor:	
Title:	HES Specialist	Approval Date:	9-22-14
E-mail Address:	Chancey.Summers@oxy.com	Expiration Date:	11-22-19
Date:	4-15-14	Conditions of Approval:	Attached <input type="checkbox"/>
Phone:	(575) 397-8216	STIC Single report	1AP-3338

Delivered & reviewed over as per NMOCD guidelines  
09-24 16696  
N701426 541802  
P701426 542112  
F701426 541640

\* Attach Additional Sheets If Necessary

SEP 22 2014