

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

SEP 22 2014

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

RECEIVED

Release Notification and Corrective Action

OPERATOR

Initial Report  Final Report

Name of Company	Oxy Permian Ltd.	Contact	CJ Summers
Address	1017 W. Stanolind Rd, Hobbs, NM	Telephone No.	(575) 397-8216
Facility Name	CE Lamunyon #41 CTB	Facility Type	Battery

Surface Owner	George Weir	Mineral Owner		API No.	30-025-22609
---------------	-------------	---------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	21	23S	37E					Lea

Latitude N 32.28411° Longitude W 103.16349°

NATURE OF RELEASE


Type of Release	Produced water	Volume of Release	10 bbls	Volume Recovered	0 bbls
Source of Release	Pump failure caused the tanks to spill over	Date and Hour of Occurrence	04/29/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Geoffrey Leking, NMOCD		
By Whom?	Kathy Purvis, BBC International	Date and Hour	04/29/14 @ 1:08 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
Pump failure caused the tanks to spill 10 bbls of produced water onto the ground. No fluids were recovered and the pump was repaired or replaced.

Describe Area Affected and Cleanup Action Taken.\*  
The affected area is approximately 300' x 150' on location. Remediation will be completed in accordance a remediation plan approved by NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	Chancey Summers	Approved by District Supervisor:	
Title:	HES Specialist	Approval Date:	9-22-14
E-mail Address:	Chancey.Summers@oxy.com	Expiration Date:	11-22-14
Date:	9-29-14	Conditions of Approval:	Attached <input type="checkbox"/>
Phone:	(575) 397-8216	Site Sample report Delivered & analyzed area as per NMOCD guidelines. Submit Final C-141 by 11-22-14.	IR# 3391 original 16698 ATO 1426 545252 P 10 1426 545363

\* Attach Additional Sheets If Necessary

SEP 22 2014