

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	Patton 17 Federal #6	Facility Type	Well location

Surface Owner	BLM	Mineral Owner		API No.	30-015-29824
---------------	-----	---------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	17	24S	31E	330	South	1800	West	Eddy County, NM

Latitude N 32.21083° Longitude W 103.80130°

NATURE OF RELEASE

Type of Release	Skim oil and Produced water	Volume of Release	1 bbl oil, 8 bbls produced water	Volume Recovered	0 bbls
Source of Release	Stuffing box on well head leaked	Date and Hour of Occurrence	01/07/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD; Jennifer Van Curen- BLM		
By Whom?	Kathy Purvis	Date and Hour	01/08/2014 @ 10:15 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

NM OIL CONSERVATION
ARTESIA DISTRICT

JUL 22 2014


RECEIVED

Describe Cause of Problem and Remedial Action Taken.*
The stuffing box on the well head leaked 1 bbl of oil and 8 bbls of produced water onto the ground. No fluids were recovered and the stuffing box issue was resolved.

Describe Area Affected and Cleanup Action Taken.*
The affected area is approximately 25' x 25' on location. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD on 04/01/2014 and approved by Jennifer Van Curen of the BLM via email on 4/22/2014.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:		Approved by Environmental Specialist:	
Printed Name:	Chancey Summers	Approval Date:	7/28/14
Title:	HES Specialist	Expiration Date:	NA
E-mail Address:	Chancey.Summers@oxy.com	Conditions of Approval:	Final
Date:	7-10-14	Phone:	(575) 397-8216
		Attached	<input type="checkbox"/>

* Attach Additional Sheets If Necessary