

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

HOBBS OGD

SEP 25 2014

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	Red Tank 34 Federal #2 CTB	Facility Type	Gathering
Surface Owner	BLM	Mineral Owner	
		API No.	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	34	22S	32E					Lea

Latitude N 32.34968° Longitude W 103.65624°

**NATURE OF RELEASE**

Type of Release	Oil	Volume of Release	30 bbls	Volume Recovered	24 bbls
Source of Release	Hammer union on 2" circulating line was replaced and was not tightened properly	Date and Hour of Occurrence	04/08/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Geoffrey Leking-NMOCD, Jennifer Van Curen-BLM		
By Whom?	Jennifer Gilkey	Date and Hour	04/09/2014 @ 5:27 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The hammer union on a 2" circulating line was replaced but not tightened properly causing 30 bbls of oil to leak onto the ground. 24 bbls of oil were recovered via vacuum truck and the hammer union was properly tightened.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 9' x 25' on location and inside the berm area around the tanks. Remediation was completed in accordance with the remediation plan approved by Tomas Oberding of NMOCD via email on 08/08/2014 and approved by Sol Hughes of the BLM via email on 08/29/2014.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<del>OIL CONSERVATION DIVISION</del>		
Printed Name: Chancey Summers	Approved by Environmental Specialist:		
Title: HES Advisor	Approval Date: 9-25-14	Expiration Date: _____	
E-mail Address: Chancey.Summers@oxy.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 9-16-14 Phone: (575) 397-8216			IRP-3225

\* Attach Additional Sheets If Necessary

n70 1422 333460  
p70 1422 334225

SEP 25 2014