

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OCD

SEP 25 2014

RECEIVED

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report


Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 TH Street	Facility Name Kiwi AKX State Battery	Telephone No. 575-748-1471
Facility Name Kiwi AKX State Battery	API Number 30-025-31576	Facility Type Battery
Surface Owner State	Mineral Owner State	Lease No. VB-134

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	16	22S	32E	2310	South	990	East	Lea

Latitude 33.39066 Longitude 103.67376

NATURE OF RELEASE

Type of Release Oil & Produced Water	Volume of Release 2 B/O & 50 B/PW	Volume Recovered 1 B/O & 15 B/PW
Source of Release Sight glass on knockout	Date and Hour of Occurrence 9/11/2010 AM	Date and Hour of Discovery 9/11/2010 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Larry Hill/NMOCD I (e-mail & voicemail)	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 9/13/2010 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Sight glass on knockout broke causing release. Vacuum truck and backhoe called.		
Describe Area Affected and Cleanup Action Taken.* An approximate area of 20' X 70'. Sight glass replaced. Oil & produced water contained within berm, battery lined with 20 mil liner. Vacuum truck recovered oil & produced water, remaining oil and produced water suspended within impacted gravel, gravel being removed and hauled to an OCD approved facility. Liner inspected. Depth to Ground Water: > 100' (340', Section 14, T22S-R23E, NMOSE); Wellhead Protection Area: No; Distance to Surface Water Body: >1000'; SITE RANKING IS 0. Based on enclosed information, Yates Petroleum Corporation requests closure.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Approved by District Supervisor: 	
Title: Environmental Regulatory Agent	Approval Date: <u>9-25-14</u>	Expiration Date: _____
E-mail Address: boba@yatespetroleum.com	Conditions of Approval: _____	Attached <input type="checkbox"/>
Date: Monday, October 04, 2010 Phone: 575-748-4217	1RP-	<u>1RP-3355</u>

* Attach Additional Sheets If Necessary

MAILED

SEP 25 2014

1701426 828689
p701426 828839