

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

HOBBS OGD

SEP 26 2014

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

RECEIVED

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company <b>COG Operating LLC</b>	Contact <b>Robert McNeil</b>
Address <b>600 West Illinois Avenue, Midland, Texas 79701</b>	Telephone No. <b>(432) 230-0077</b>
Facility Name <b>Crockett State #2H</b>	Facility Type <b>Tank Battery</b>

Surface Owner: State	Mineral Owner	Lease No. (API#) <b>30-025-41080</b>
----------------------	---------------	--------------------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	20	20S	33E					Lea

Latitude N 32.46523 ° Longitude W 103.58663°

**NATURE OF RELEASE**



Type of Release: Oil and Produced Water	Volume of Release <b>7bbls oil 120bbls produced water</b>	Volume Recovered <b>5bbls oil 15bbls produced water</b>
Source of Release <b>Load Line</b>	Date and Hour of Occurrence <b>1-25-2014</b>	Date and Hour of Discovery <b>1-25-2014 11:00am</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Mike Bratcher - NMOCD</b>	
By Whom? Robert Grubbs Jr.	Date and Hour <b>1-26-2014 4:58 pm</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\*  
Someone opened the load line going to the water tank. Closed the valve.

Describe Area Affected and Cleanup Action Taken.\*  
Initially 7 bbls of oil and 120 bbls or produced water were released. We were able to recover 5 bbls of oil and 15 bbls of produced water with a vacuum truck. All free fluids were recovered. Tetra Tech inspected site and collected samples to define spills extent. Soil that exceeded RRAL was removed and hauled away for proper disposal. Site was then brought up to surface grade with clean backfill material. Tetra Tech prepared closure report and submitted to NMOCD for review.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Ike Tavarez	Approved by District Supervisor: 	
Title: Senior Project Manager, P.G.	Approval Date: <b>9-26-14</b>	Expiration Date: <b>←</b>
E-mail Address: <a href="mailto:ike.tavarez@tetratech.com">ike.tavarez@tetratech.com</a>	Conditions of Approval: <b>—</b>	
Date: <b>9-12-14</b> Phone: (432) 682-4559	Attached <input type="checkbox"/> <b>IRP -3358</b>	

\* Attach Additional Sheets If Necessary

SEP 26 2014

Sign 229132  
7701426 941288  
P701426 941971