

HOBBS OCD

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
320 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company: Targa Midstream Services L.P.	Contact: Bill Little 575.394.2534 Chuck Tolsma 575.631.6026
Address: PO Box 1909 Eunice, NM 88231	Telephone No.: (575) 394-2534
Facility Name: Eunice Gas Plant	Facility Type: Natural Gas Gathering System
Surface Owner: Priscilla West	Mineral Owner
Lease No. 30-025-24650	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Fcct from the	North/South Line	Fcct from the	East/West Line	County
	4	22S	37E					

Latitude: N 32.426747 Longitude: W 103.168565

NATURE OF RELEASE

Type of Release: Brine Water from 4" disposal line	Volume of Release: Unknown	Volume Recovered: 80 bbls
Source of Release: 4" disposal line	Date and Hour of Occurrence: Unknown	Date and Hour of Discovery: 08:33 02/28/14
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoffrey Leking with OCD in Hobbs by phone (message) Mark Whitaker with OCD in Hobbs by phone (message)	
By Whom?	Date and Hour 10:00AM 02/28/14	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* 1/2" hole in 4" brine water disposal line. Approximately 2200 yards of contaminated soil was removed and hauled to an OCD approved landfill (Sundance services)

Describe Area Affected and Cleanup Action Taken.* The area affected has been excavated and soil contamination disposed of at an approved OCD landfill (Sundance Services). A 20ml liner was installed in the bottom of the excavation after approval on July 18, 2014 from the OCD Hobbs. The excavation was backfilled with clean soil and leveled.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rebecca Woodell</i>	OIL CONSERVATION DIVISION	
Printed Name: Rebecca Woodell	Approved by District Supervisor: <i>[Signature]</i>	
Title: ES&H Specialist	Approval Date: 10-8-14	Expiration Date: _____
E-mail Address: rwoodell@targaresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: July 18, 2014 Phone: (575) 394-2534 ext 239		100-3190 09018 873 770 19 14 947500 P 70 19 14 947681

* Attach Additional Sheets If Necessary

OCT 08 2014