

HOBBS OCD

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company EOG Resources, Inc.	Contact Zane Kurtz
Address 5509 Champions Drive, Midland, TX 79706	Telephone No. 432-425-2023
Facility Name Madera Pipeline	Facility Type Pipeline off pad and along the haul road

Surface Owner New Mexico	Mineral Owner New Mexico	API No.
--------------------------	--------------------------	---------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	25	T24S	R33E	2960'	N	1895'	W	Lea

Latitude 32.1876 Longitude -103.528411

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release Unknown	Volume Recovered Unknown
Source of Release Poly Line leaked	Date and Hour of Occurrence Unknown	Date and Hour of Discovery Unknown
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
According to our limited records, There was a small produced water leak from a poly line. CRA went out and collected soil samples and the north wall near a pipeline ROW had elevated chlorides concentrations. Area is on north side of lease road between Madera Ridge 25 #1 and Vaca Lane.

Describe Area Affected and Cleanup Action Taken.*
The site is currently excavated with the stockpiled soil sitting on poly plastic. CRA recommended that we submit the figure and this C-141 and ask for guidance and see if we could backfill with clean soil to grade and dispose of stockpile to Sundance Landfill.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Zane Kurtz	Approved by Environmental Specialist:	
Title: Sr. Safety and Environmental Rep., EOG Resources, Inc.	Approval Date: 10-8-14	Expiration Date: 12-8-14
E-mail Address: zane_kurtz@eogresources.com	Conditions of Approval: SITE Sample Request	Attached <input type="checkbox"/>
Date: 10-02-2014 Phone: 432-425-2023		1RP-3368

* Attach Additional Sheets If Necessary

Relocate & conduct over on
per NMOCD Grade. Submit
Final C-141 by 12-8-14
OG-14 7377
F70142813 3007
N701428 13364
P701428 133756

OCT 08 2014