

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

OCT 13 2014

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1428742057
Name of Company: COG Operating LLC *229137* OPERATOR Initial Report Final Report
Address: 600 West Illinois Avenue, Midland TX 79701 Contact: Robert McNeill
Facility Name: McIntyre DK #15 Telephone No. 432-230-0077
Facility Type: Battery

Surface Owner: Federal Mineral Owner: Federal API No. 30-015-40896

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	17	17S	30E	261'	South	2618'	West	Eddy

Latitude 32.8280730541828 Longitude -103.994208840473

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 30 bbls Oil ; 60 bbls PW	Volume Recovered: 29 bbls Oil ; 59 bbls PW
Source of Release: Gasket Failure	Date and Hour of Occurrence: 10-10-2014 5:30 am	Date and Hour of Discovery: 10-10-2014 5:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - OCD / Jim Amos - BLM	
By Whom? Amanda Trujillo	Date and Hour: 10-13-2014 9:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A gasket failure on a heater treater caused the release. This release occurred within a lined facility, however an overspray of 20' x 40' impacted the pasture to the south. No standing pools formed as a result of the spray. Vacuum trucks were dispatched to pick up all standing fluid in berm and dispose of at an NMOCD approved facility.

Describe Area Affected and Cleanup Action Taken.*

Once all standing fluid was retrieved an pressure washer cleaned equipment and removed gravel. The pasture was treated with soapy water on vegetation and Microblaze on the soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>A Trujillo</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist <i>Mike Bratcher</i>	
Title: Senior Environmental Coordinator	Approval Date:	Expiration Date:
E-mail Address: atrujillo@concho.com	Conditions of Approval:	
Date: October 13, 2014 Phone: 575-748-6940	Attached <input type="checkbox"/>	

LIKE APPROVAL BY
BLM

2292548

* Attach Additional Sheets If Necessary

Patterson, Heather, EMNRD

From: Amanda Trujillo <ATrujillo@concho.com>
Sent: Monday, October 13, 2014 8:22 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; james_amos@blm.gov; jlobertson@blm.gov
Subject: (Notification) McIntyre DK Federal #15 (30-015-40896)
Attachments: 10-10-2014 McIntyre DK #15 (TB) Inital-Final.pdf

Mr. Bratcher/Mr. Amos,

COG Operating LLC is reporting a release on the McIntyre DK Federal #15 (30-015-40896).

Unit N Section 17 Township 17S Range 30E

The release occurred at 5:30 am on 10/10/2014.

Released: 30 bbls Oil ; 60 bbls PW

Recovered: 29 bbls Oil ; 59 bbls PW

The release was caused by a gasket failure. This release occurred within a lined facility; however an overspray of 20' x 40' impacted the pasture to the south. No standing pools formed as a result of the spray. Once all standing fluid was retrieved a pressure washer cleaned equipment and removed gravel. The pasture was treated with soapy water on vegetation and Microblaze on the soil. Attached is a C-141 for your consideration. If you have any additional questions please feel free to contact me.

Thank you,

Amanda Trujillo

Senior Environmental Coordinator

COG Operating LLC

Cell: 505.350.1336

Office: 575.748.6930

atrujillo@concho.com

2208 W. Main St.

Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.