

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION**

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

OCT 14 2014

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

# NAB142.8749671 OPERATOR  Initial Report  Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 <sup>th</sup> Street	Telephone No. 575-748-1471	
Facility Name Corral Draw AQH Federal #1	Facility Type Battery	

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-29396
--------------------------	--------------------------	-------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	13	24S	29E	2310	South	330	West	Eddy

Latitude 32.21642 Longitude 103.94524

**NATURE OF RELEASE**

Type of Release Crude Oil	Volume of Release 15 B/O	Volume Recovered 15 B/O
Source of Release Circulation pump	Date and Hour of Occurrence 9/26/2014; AM	Date and Hour of Discovery 9/26/2014; AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOCD II	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 9/27/2014; AM (Email)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The circulation pump has a bad swedge on discharge. Vacuum truck(s) and roustabout crew called.

Describe Area Affected and Cleanup Action Taken.\*

An approximate area of 30' x 30'. The circulation pump was repaired and all of the released crude oil was recovered using a vacuum truck. Impacted soils excavated to stop vertical migration of any contaminants. **Depth to Ground Water: >100' (approximately 125', per ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0. Based on site ranking of /DTGW >100', impacted soils excavated and all crude oil was recovered, Yates Petroleum Corporation requests closure.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Robert Asher	Approved by Environmental Specialist 	
Title: NM Environmental Regulatory Supervisor	Approval Date:	Expiration Date:
E-mail Address: boba@yatespetroleum.com	Conditions of Approval:	
Date: October 13, 2014 Phone: 575-748-4217	2RP- <b>FINAL</b>	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

2RP-255

**Patterson, Heather, EMNRD**

---

**From:** Tanna Adams <TCAdams@yatespetroleum.com>  
**Sent:** Tuesday, October 14, 2014 8:15 AM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Patterson, Heather, EMNRD; Bob Asher  
**Subject:** Corral Draw AQH Federal #1 C141  
**Attachments:** Corral Draw AQH Federal #1.pdf

Mr. Bratcher,

Please find attached the signed C141 Initial/Final for the below listed location:

**Corral Draw AQH Federal #1**  
**30-015-29396**  
**Section 13, T24S-R29E**  
**2310 FSL & 330 FWL**  
**Eddy County, New Mexico**

Thank you,

*Tanna Adams*  
Yates Petroleum Corporation  
Environmental Tech  
Environmental Department  
[TCAdams@yatespetroleum.com](mailto:TCAdams@yatespetroleum.com)

---

**This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.**

---