


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Alamo Permian Resources, LLC	Contact	Steven Mastin
Address	415 W. Wall St. Suite 500	Telephone No.	(432) 5557-5847
Facility Name	West Artesia Grayburg Unit 13	Facility Type	Injection Line

Surface Owner: State	Mineral Owner	Lease No. (API#) 30-015-02636
----------------------	---------------	-------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	7	18S	28E	2310	S	330	E	Eddy

Latitude N 32.7603500° Longitude W 104.2067700°

NATURE OF RELEASE

Type of Release: Brine Water	Volume of Release: Est 40 bbls	Volume Recovered 0 bbls
Source of Release: Flowline	Date and Hour of Occurrence 03/15/2012	Date and Hour of Discovery 03/15/2012 1:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Ricky Rodriguez	Date and Hour 03/315/2012 1:00 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The leak in the flowline was repaired and the line was put back into service. Alamo scraped the area using a backhoe.

Describe Area Affected and Cleanup Action Taken.*
Tetra Tech personnel inspected the site and collected samples to define the spills extent. Soil that exceeded the RRAL was removed and hauled away for proper disposal. The site was then lined and brought up to surface grade with clean backfill material. Tetra Tech prepared a closure report and submitted it to NMOCD for review.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:	Approved by District Supervisor:	
Printed Name: Ike Tavaréz	Approval Date: 9/8/14	Expiration Date: NA
Title: Project Manager	Conditions of Approval: Final	
E-mail Address: Ike.Tavaréz@TetraTech.com	Attached <input type="checkbox"/>	
Date:	Phone: (432) 682-4559	

* Attach Additional Sheets If Necessary

2RP-1070