

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Oxy Permian Ltd.	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	Roo 22 State #13	Facility Type	Well Location

Surface Owner	State	Mineral Owner		API No.	30-015-40535
---------------	-------	---------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	22	17S	28E	787	North	2023	West	Eddy County, NM

Latitude N 32.81631° Longitude W 104.17°

NATURE OF RELEASE


Type of Release	Oil and Produced water	Volume of Release	7 bbls oil, 33 bbls produced water	Volume Recovered	Unknown
Source of Release	Valve open, handle off, bull plug missing	Date and Hour of Occurrence	12/28/2013	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD		
By Whom?	Jennifer Gilkey, BBC International	Date and Hour	12/30/2013 @ 12:45 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
For an unknown reason, a valve was left open, a handle was off, and a bull plug was missing at the well head which caused 7 bbls of oil and 33 bbls of produced water to leak onto the ground. All free-standing fluids were recovered via vacuum truck and the well head parts were repaired and/or replaced.

Describe Area Affected and Cleanup Action Taken.*
The affected area is approximately 10' x 20' on location. Remediation was completed in accordance with a remediation plan verbally approved by Mike Bratcher of NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Christopher Jones		Approved by District Supervisor:	
Title: HES Specialist	Approval Date: 8/22/14	Expiration Date: NA	
E-mail Address: Christopher_Jones@oxy.com	Conditions of Approval: Final	Attached <input type="checkbox"/>	
Date: 3/31/14	Phone: (575) 628-4121		

* Attach Additional Sheets If Necessary

22P-2154