

OCT 10 2014

RECEIVED

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 E. First St., Ariesa, NM 88210
District III
1000 Rio Arriba Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 3, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Oxy Permian Ltd.	Contact: Austin Trammell
Address: 1017 W. Stinson Rd, Hobbs, NM 88240	Telephone No.: (575) 499-4919
Facility Name: West Dollahide Devonian Unit #121	Facility Type: Well location

Surface Owner:	Mineral Owner:	API No.: 30-025-28771
----------------	----------------	-----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	33	24S	30E	1285	North	1650	West	Lea

Latitude: N 32.17727° Longitude: W 103.06815°

NATURE OF RELEASE

Type of Release: Oil and Produced water	Volume of Release: 5 bbls oil, 5 bbls produced water	Volume Recovered: 3 bbls oil, 3 bbls produced water
Source of Release: Tank spilled over	Date and Hour of Occurrence: 01/09/2014	Date and Hour of Discovery:
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoffrey Laking-NMOCOD	
By Whom?: Austin Trammell	Date and Hour: 01/09/2014 @ 10:54 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse:	
If a Watercourse was Impacted, Describe Fully: NO		
Describe Cause of Problem and Remedial Action Taken: A tank spilled over and leak 5 bbls of oil and 5 bbls of produced water onto the ground. 3 bbls of oil and 3 bbls of produced water were recovered via vacuum truck and the cause of the tank spill was corrected.		
Describe Area Affected and Cleanup Action Taken: The affected area is approximately 10' x 30' on location. Remediation will be completed in accordance with an approved remediation plan from NMOCOD.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCOD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCOD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCOD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>Austin Trammell</i>	OIL CONSERVATION DIVISION	
Printed Name: Austin Trammell	Approved by Environmental Specialist:	
Title: HES Coordinator	Approval Date: 10-10-14	Expiration Date: 12-10-14
E-mail Address: Austin.Trammell@oxy.com	Conditions of Approval: Site Super sign Release & route as us per NMOCOD guide sheet form C-141 by 12-10-14	Attached <input type="checkbox"/> 10P-3375 Ogrid 16696 A701428727889 P701428728093

* Attach Additional Sheets If Necessary

OCT 17 2014