

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD
State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505
OCT 16 2014
RECEIVED

Form C-141
Revised August 8, 2011
Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Loco Hills SWD System	Facility Type: Pipeline

Surface Owner: Federal	Mineral Owner:	API No.
------------------------	----------------	---------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	21	17S	32E	2460'	North	330'	East	Lea

Latitude N32°49.228' Longitude W103°45.769'

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 300 bbls PW	Volume Recovered: 280 bbls PW
Source of Release: SWD Pipeline	Date and Hour of Occurrence: 10/7/2014 12:50 pm	Date and Hour of Discovery: 10/7/2014 12:50 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD / Jeffery Robertson - BLM	
By Whom? Amanda Trujillo	Date and Hour: 10/8/2014 4:36 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

While installing risers on a COG SWD mainline Legendary Pipeline Co struck a 6" waterline with their bucket. Approximately 300bbls of produced water, contained in 70'x40' dug out in COG ROW. Vacuum trucks were dispatched to recover all standing fluid.

Describe Area Affected and Cleanup Action Taken.*

The impacted area is contained to a 70'x60' area within an excavation. Vacuum trucks removed all standing fluid and disposed of at an NMOCD approved facility. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: *A Trujillo*

Printed Name: Amanda Trujillo

Approved by Environmental Specialist:

Title: Senior Environmental Coordinator

Approval Date: 10-16-14

Expiration Date: 12-16-14

E-mail Address: atrujillo@concho.com

Conditions of Approval:

Attached

Date: October 13, 2014 Phone: 575-748-6940

*State Supplement request
Relevant remediate area as per
NMOCD guidance. Submit final
C-141 by 12-16-14*

IRP-3384
0710 229137
F701428 94 6386
N701428 94 6944
P701428 94 7513

* Attach Additional Sheets If Necessary

OCT 17 2014