

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OGD

OCT 20 2014

RECEIVED

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Oxy USA Inc.	Contact	Austin Tramell
Address	1017 W. Stanolind Rd, Hobbs, NM	Telephone No.	(575) 397-8210
Facility Name	Federal 27 #8	Facility Type	Well

Surface Owner	BLM	Mineral Owner		Lease No.	30-025-32755
---------------	-----	---------------	--	-----------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	27	22S	32E	580'	South	790'	West	Lea

Latitude N 32.35681° Longitude W 103.6680°

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	15 bbls	Volume Recovered	0 bbls
Source of Release	Stuffing box leak on well head	Date and Hour of Occurrence	02/18/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Goeffrey Leking- NMOCD, Jennifer Van Curen- BLM		
By Whom?	Kathy Purvis, BBC International	Date and Hour	02/18/2014 @ 3:20 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
The stuffing box on the well head leaked 15 bbls of produced water onto the ground. No fluids were recovered and the stuffing box was repaired.

Describe Area Affected and Cleanup Action Taken.*
The affected area was approximately 20' x 60' on the location pad and 2' x 15' off the location pad. Remediation will be completed in accordance with a plan approved by both the NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Austin Tramell	Approved by District Supervisor:	
Title:	HES Coordinator	Approval Date:	10-20-14
		Expiration Date:	12-20-14
E-mail Address:	Austin.Tramell@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date:	2/19/14	Phone: (575) 397-8210	1AP-3387

* Attach Additional Sheets If Necessary

Site Supervisor report
Beckwith & radiate area upon
NMOCD guide. Submit final
C-141 by 12-20-14

OGD 16696
N-7014 29 333197
A7014 29 333643

OCT 17 2014