

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**HOBBS OCD**  
State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**HOBBS OCD** 70  
Form C-141  
Revised October 10, 2003  
OCT 17 2014  
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

**Release Notification and Corrective Action**

**OPERATOR**  Initial Report  Final Report

Name of Company Oxy USA Inc.	Contact Chancey Summers
Address 1017 W. Stanolind Rd, Hobbs, NM	Telephone No. (575) 397-8216
Facility Name Federal 27 #8	Facility Type Well

Surface Owner BLM	Mineral Owner	API No. 30-025-32755
-------------------	---------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	27	22S	32E	580'	South	790'	West	Lea

Latitude N 32.35681° Longitude W 103.6680°

**NATURE OF RELEASE**

Type of Release Produced Water	Volume of Release 15 bbls	Volume Recovered 0 bbls
Source of Release Stuffing box leak on well head	Date and Hour of Occurrence 02/18/2014	Date and Hour of Discovery
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoffrey Leking- NMOCD, Jennifer Van Curen- BLM	
By Whom? Kathy Purvis, BBC International	Date and Hour 02/18/2014 @ 3:20 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
The stuffing box on the well head leaked 15 bbls of produced water onto the ground. No fluids were recovered and the stuffing box was repaired.

Describe Area Affected and Cleanup Action Taken.\*  
The affected area was approximately 20' x 60' on the location pad and 2' x 15' off the location pad. Remediation was completed in accordance with the remediation plan approved by Geoffrey Leking of NMOCD via email on 07/01/2014 and approved by Jennifer Van Curen in a meeting on 06/30/2014.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Chancey Summers	Approved by District Supervisor. 	
Title: HES Advisor	Approval Date: 10-20-14	Expiration Date: _____
E-mail Address: Chancey_Summers@oxy.com	Conditions of Approval: _____	
Date: 10-10-14 Phone: (575) 397-8216	Attached <input type="checkbox"/> RP-3387	

\* Attach Additional Sheets If Necessary

09-14 16696  
RTO 1429 333147  
P 70 14 29 333643

OCT 17 2014