

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION**  
ARTESIA DISTRICT

OCT 20 2014

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.  
**RECEIVED**

**Release Notification and Corrective Action**

*NAB1429431102A*

**OPERATOR**

Initial Report  Final Report

Name of Company: COG Operating LLC #229137	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Honey Graham State Com #1H	Facility Type: Battery

Surface Owner: State	Mineral Owner: State	API No. 30-015-37465
----------------------	----------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	29	26S	28E	330	North	660	West	Eddy

Latitude 32.018610330935 Longitude -104.11702930695

**NATURE OF RELEASE**

Type of Release: Oil and Produced Water	Volume of Release: 353 bbls Oil ; 60 bbls PW	Volume Recovered: 0 bbls Oil ; 0 bbls PW
Source of Release: Flood damaged battery	Date and Hour of Occurrence: 9/19/2014	Date and Hour of Discovery: 10-6-2014 12:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - OCD	
By Whom? Robert McNeill	Date and Hour: 9/22/2014 8:00 am (phone call)	
Was a Watercourse Reached? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse. Unknown	

If a Watercourse was Impacted, Describe Fully.\*  
Torrential rains caused flood waters to rise. Waters over ran the location, broke tank drain lines. This location was inaccessible for several weeks.

Describe Cause of Problem and Remedial Action Taken.\*

Describe Area Affected and Cleanup Action Taken.\*

The impacted area shows no signs of hydrocarbon or brine impact. Once the area dries out and is accessible to heavy equipment we will conduct a more thorough search of the area for hydrocarbon impact. Equipment will be removed from the draw and disposed of at an NMOCD approved facility.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>A Trujillo</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: <i>Huck</i>	
Title: Senior Environmental Coordinator	Approval Date: <i>10/21/14</i>	Expiration Date: <i>NA</i>
E-mail Address: atrujillo@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: October 20, 2014 Phone: 575-748-6940	<b>Remediation per O.C.D. Rules &amp; Guidelines</b>	

**SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 11/21/14**

\* Attach Additional Sheets If Necessary

*22P-2559*

## **Bratcher, Mike, EMNRD**

---

**From:** Amanda Trujillo <ATrujillo@concho.com>  
**Sent:** Monday, October 20, 2014 5:00 PM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD  
**Subject:** (Initial C-141) Honey Graham State Com #1H (30-015-37465)  
**Attachments:** 10-6-2014 Honey Graham State Com #1H (TB) Initial.pdf

Mr. Bratcher,

COG Operating LLC is reported the release at the **Honey Graham State Com #1H (30-015-37465)** on 9/22/2014 by phone.

Unit D Section 29 Township 26S Range 28E

The release occurred on 09/19/2014.

**Released:** 353 bbls Oil; 60 bbls Produced Water

**Recovered:** 0 bbls Recovered

This release was caused by torrential rains. Waters over ran the location, braking the tank drain lines. This location was in accessible for several weeks. Attached is a C-141 Initial for your consideration. If you have any additional questions please feel free to contact me.

Thank you,

### **Amanda Trujillo**

Senior Environmental Coordinator

COG Operating LLC

Cell: 505.350.1336

Office: 575.748.6930

[atrujillo@concho.com](mailto:atrujillo@concho.com)

2208 W. Main St.

Artesia , NM 88210



**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.