

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company Southern Union Gas Services	Contact Crystal D. Callaway
Address 801 South Loop 464, Monahans, TX, 79756	Telephone No. (817) 302-9407
Facility Name: Trunk "O" #5 (RP-1523)	Facility Type Natural Gas Gathering

Surface Owner: Beverly Jean Bull	Mineral Owner Fee	API No.
----------------------------------	-------------------	---------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	34	22S	36E					Lea

Latitude 32 20.714 Longitude -103 15.256

**NATURE OF RELEASE**

Type of Release: Crude Oil, Produced water, and Natural Gas	Volume of Release: 550 bbls Fluid and 945 Mcf Nat. Gas	Volume Recovered: 500 bbls crude oil and produced water
Source of Release: 30" Natural Gas Pipeline	Date and Hour of Occurrence: 7/23/07 4:15 p.m.	Date and Hour of Discovery: 7/23/07 Time: 4:15 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Gary Wink the NMOCD on call representative	
By Whom? Tony Savoie	Date and Hour 7/23/07 4:35 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

**Describe Cause of Problem and Remedial Action Taken**


A 30" Natural Gas gathering line developed a leak due to excess fluid delivered by a producer caused the line to pressure up and leak fluid and natural gas. Crews were repairing a section of line in this area when the leak occurred; a vacuum truck was on hand and started removing fluid within 15 minutes of the pipe failure. Most of the fluid was contained to the bell-hole in the lease road and a large depression in the lease road.

**Describe Area Affected and Cleanup Action Taken.\*** Approximately 6200 Square feet of pasture land and approximately 7200 square feet of caliche lease road were impacted by the release. Approximately 500 bbls of mostly produced water and crude oil were recovered during the temporary clamping event. The final remediation will follow the NMOCD Guidelines for the remediation of leaks and spills.

Laboratory analytical results from confirmation soil samples collected from the excavation floor and sidewalls were sent to an NMOCD approved laboratory which determined concentrations of BTEX, TPH and chloride where less than NMOCD regulatory standards.

Please see the attached Basin Environmental Services Technologies Remediation Summary and Site Closure Request for details of remedial activities and laboratory analytical results from confirmation soil sampling.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Crystal D. Callaway	Approved by Environmental Specialist:	
Title: Senior Environmental Remediation Specialist	Approval Date: 10-23-14	Expiration Date: _____
E-mail Address: Crystal.Callaway@Regencygas.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10/08/2014 Phone: (817) 302-9407		IRP-1523

21232  
PRAC 0722130726

OCT 27 2014