

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

OCT 24 2014

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
RECEIVED accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1430052013

OPERATOR Initial Report Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: BKU Central Tank Battery SWD (<i>BKV221</i>)	Facility Type: Facility

Surface Owner: Fee Mineral Owner: Fee API No. N/A *30-015-27764*

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	24	17S	29E	N/A	N/A	N/A	N/A	Eddy

32.8177 Latitude N32° 49.180 Longitude W104° 01.569 *104,0262*

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 45 bbls PW	Volume Recovered: 40 bbls PW
Source of Release: Pump failure	Date and Hour of Occurrence: 10-10-2014 12:00 pm	Date and Hour of Discovery: 10-10-2014 12:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - OCD	
By Whom? Amanda Trujillo	Date and Hour: 10-16-2014 8:01 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The release was caused by a plunger on a triplex pump failing. Vacuum trucks were dispatched to remove any standing fluids and the pump was replaced.

Describe Area Affected and Cleanup Action Taken.*

The impacted area was within the bermed facility in an area approximately 10'x30'. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>A Trujillo</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: <i>He Pen</i>	
Title: Senior Environmental Coordinator	Approval Date: <i>10/27/14</i>	Expiration Date: <i>NA</i>
E-mail Address: atrujillo@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: October 24, 2014 Phone: 575-748-6940	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

RECEIVED
SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 11/27/14

2RP-2565

Patterson, Heather, EMNRD

From: Amanda Trujillo <ATrujillo@concho.com>
Sent: Friday, October 24, 2014 4:16 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Subject: (C-141 Initial) Burch Keely Water Flood Central Tank Battery

Mr. Bratcher,

Attached is a C-141 for your consideration. Please feel free to contact me if you have any questions or concerns.

Thank you,

Amanda Trujillo

Senior Environmental Coordinator
COG Operating LLC
Cell: 505.350.1336
Office: 575.748.6930
atrujillo@concho.com

2407 Pecos Ave.
Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

From: Amanda Trujillo
Sent: Wednesday, October 15, 2014 8:01 PM
To: Bratcher, Mike, EMNRD; 'Patterson, Heather, EMNRD'
Subject: (Notification) Burch Keely Water flood Central Tank Battery

Mr. Bratcher,

COG Operating LLC is reporting a release on the Burch Keely Water flood Central Tank Battery
Section 24 Township 24S Range 29E
The release occurred at 12:00 pm on 10/10/2014.

Released: Produced Water 45 bbls

Recovered: Produced Water 40 bbls

The release was caused by a pump failure. The site is being evaluated for clean-up and a C-141 will be submitted. If you have any additional questions please feel free to contact me.

Thank you,

Amanda Trujillo

Senior Environmental Coordinator

COG Operating LLC

Cell: 505.350.1336

Office: 575.748.6930

atrujillo@concho.com

2208 W. Main St.

Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.