

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*NAB1430728086*

**OPERATOR**  Initial Report  Final Report

Name of Company- Nadel and Gussman HEYCO, LLC *258462* Contact- Tammy R. Link  
Address - P.O. Box 1936, Roswell, NM 88201-1936 Telephone No. 575-623-6601  
Facility Name - Cannonball #1H Facility Type - API #30-015-38569 \*  
Surface Owner - State Mineral Owner *? Well* \*API No. *30-015-38569*

**LOCATION OF RELEASE**

Unit Letter H	Section 20	Township 18S	Range 26E	Feet from the 1980'	North/South Line N	Feet from the 330'	East/West Line E	County Eddy
------------------	---------------	-----------------	--------------	------------------------	-----------------------	-----------------------	---------------------	----------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release - Oil Spill	Volume of Release - 7 bbls	Volume Recovered 5 bbls
Source of Release	Date and Hour of Occurrence N/A	Date and Hour of Discovery-10/29/14 8:30 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

**NM OIL CONSERVATION**  
ARTESIA DISTRICT  
OCT 31 2014

Describe Cause of Problem and Remedial Action Taken.\*

Hole in bottom of tank.

**RECEIVED**

Describe Area Affected and Cleanup Action Taken.\*

Vacuumed oil up and back into tank, clean up area inside of dike put fresh gravel around area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tammy R. Link</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Tammy R. Link	Signed By: <i>Mike Brando</i> Approved by Environmental Specialist.	
Title: Engineering Tech	Approval Date: <i>11/3/14</i>	Expiration Date:
E-mail Address: tlink@heycoenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>

Date: 10/29/2014 Phone: 575-623-6601

**Remediation per O.C.D. Rules & Guidelines**  
**SUBMIT REMEDIATION PROPOSAL NO**  
**LATER THAN: *12/3/14***

\* Attach Additional Sheets If Necessary

*2RP-2568*