

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

OCT 02 2014

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1430851048

OPERATOR

Initial Report Final Report

Name of Company: COG Operating LLC <i>217955</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Cabo Wabo 25 Federal #1H	Facility Type: Battery

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-40440
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	25	25S	29E	330'	North	600'	West	Eddy

Latitude 32.1072402109889 Longitude -103.944639787162

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 120 bbls	Volume Recovered: 115 bbls
Source of Release: Lightning struck water tank	Date and Hour of Occurrence: 9/19/2014 4:30	Date and Hour of Discovery: 9/19/2014 4:30
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Robert McNeill	Date and Hour: 9/22/2014 8:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
During the flooding, lightning struck the water tank and caused a fire. Due to the flooding fire crews were unable to reach the location. The fire burned itself out. Fluids were contained within the lined berm, vacuum trucks were dispatched to recover standing fluid.

Describe Area Affected and Cleanup Action Taken.*
The release was contained within the lined bermed area. A new tank will be placed in the facility and it will be returned to previous working condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>A Trujillo</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: <i>Mike Brandon</i>	
Title: Senior Environmental Coordinator	Approval Date: <i>11/4/14</i>	Expiration Date: <i>N/A</i>
E-mail Address: atrujillo@concho.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: October 2, 2014 Phone: 575-748-6940		

* Attach Additional Sheets If Necessary

2RP-2573

Patterson, Heather, EMNRD

From: Amanda Trujillo <ATrujillo@concho.com>
Sent: Thursday, October 02, 2014 2:26 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; james_amos@blm.gov; jlrobertson@blm.gov
Subject: (Initial-Final C-141) Cabo Wabo 25 Federal #1H (30-015-40440)
Attachments: 09-19-2014 Cabo Wabo 25 Federal #1H (TB) Initial-Final.pdf

Mr. Bratcher/Mr. Amos,

COG Operating LLC is reported the release at the **Cabo Wabo 25 Federal #1H (30-015-40440)** on 9/22/2014 by phone. Unit D Section 25 Township 25S Range 29E

The release occurred at 4:30 pm on 09/19/2014.

Released: 120 bbls Produced Water

Recovered: 115 bbls Produced Water

This release was caused by a lightning strike that resulted in a fire. All fluids were contained within a lined facility.

Attached is a C-141 Initial for your consideration. If you have any additional questions please feel free to contact me.

Thank you,

Amanda Trujillo

Senior Environmental Coordinator

COG Operating LLC

Cell: 505.350.1336

Office: 575.748.6930

atrujillo@concho.com

2208 W. Main St.

Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.