

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

HOBBS OGD

NOV 05 2014

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action
RECEIVED

OPERATOR

Initial Report Final Report

Name of Company	Southern Union Gas Services, Ltd.	Contact	Crystal Callaway
Address	801 S. Loop 464, Monahans, TX, 79756	Telephone No.	(817) 302-9407
Facility Name:	Trunk "O" 30" (RP-1817 and RP-1801)	Facility Type	Natural Gas Gathering

Surface Owner	State of N.M.	Mineral Owner:	State of N.M.	Lease No.
---------------	---------------	----------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	5	21S	36E					Lea

Latitude N32 30.258

Longitude W103 17.165

NATURE OF RELEASE

Type of Release:	Natural Gas and Produced water	Volume of Release	Unknown	Volume Recovered	None
Source of Release:	30" Natural Gas Pipeline	Date and Hour of Occurrence	Not known	Date and Hour of Discovery	2/20/08 Time: 9:45 a.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour:			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken:

A 30" Natural Gas gathering line operating at approximately 30 p.s.i. developed a leak. Date and time of loss is unknown, the leak area was discovered during a pipeline replacement.

Describe Area Affected and Cleanup Action Taken.* An area of pasture land measuring approximately 4,500 sq.ft. has discolored soil in the backfill material, the soil is dark to light gray in appearance. Final remediation will follow the NMOCD recommended guidelines for leaks and spills.

Confirmation soil samples collected from the Trunk "O" 30" Historical Remediation site indicate concentrations of BTEX, TPH and chloride are less than NMOCD Regulatory Standards.

Please reference the attached Basin Environmental Services Technologies Remediation Summary and Site Closure Request for details of remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases, which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Crystal Callaway	Approved by District Supervisor: 	
Title: Senior Environmental Remediation Specialist	Approval Date: 11-5-14	Expiration Date: _____
E-mail Address: Crystal.Callaway@Regencygas.com	Conditions of Approval: _____	
Date: 10/31/14	Phone: (817) 302-9407	IRP-1801

NOV 10 2014