

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

08 08 2014

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

† JMW1328229138

Release Notification and Corrective Action

Name of Company Yates Petroleum Corporation		Contact Chase Settle	
Address 104 S. 4 th Street		Telephone No. 575-748-1471	
Facility Name Central Dagger Draw Water Station		Facility Type Water Transfer Station	

Initial Report Final Report

Surface Owner Federal	Mineral Owner Federal	API No. N/A
--------------------------	--------------------------	----------------

LOCATION OF RELEASE

Unit Letter 1	Section 3	Township 20S	Range 24E	Feet from the 2080	North/South Line South	Feet from the 660	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.60096 Longitude -104.56909

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 20 B/PW	Volume Recovered 10 B/PW
Source of Release Overflow of a produced water tank	Date and Hour of Occurrence 9/23/2014; AM	Date and Hour of Discovery 9/23/2014; AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

The produced water tank overflowed and strong rains caused the release to flow over a lined battery berm into an unlined, second portion of bermed battery in front of the pump house. Valves were shut, equalizer valves for other tanks were opened, vacuum truck(s) and roustabout crew called.

Describe Area Affected and Cleanup Action Taken.*

An approximate area of 150 x 105 feet was affected within the bermed battery, with 50 x 45 feet being on the lined portion of the tank battery berm. The valves leading to the overflowing tank were closed and equalizer valves to the other tanks opened. Vacuum trucks were called to recover any standing fluid. Excavated soils will be hauled to a NMOCD approved facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX (chlorides for documentation). If initial analytical results for TPH & BTEX are under RRAL's (site ranking is 0) a Final Report, C-141 will be submitted to the OCD requesting closure. **Depth to Ground Water: >100'(approximately 228', Section 3, T20S-R24E, per Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS ZERO (0).**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Chase Settle	Approved by Environmental Specialist: 	
Title: NM Environmental Regulatory Agent	Approval Date: <u>10/9/14</u>	Expiration Date: <u>NA</u>
E-mail Address: CSettle@yatespetroleum.com	Conditions of Approval: <input type="checkbox"/> Attached <input type="checkbox"/>	
Date: October 8, 2014	Remediation per O.C.D. Rules & Guidelines	
Phone: 575-748-4217	SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

ATER THAN: 12/9/14

2 RP 2591

Patterson, Heather, EMNRD

From: Chase Settle <CSettle@yatespetroleum.com>
Sent: Wednesday, October 08, 2014 6:28 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Bob Asher; Tanna Adams
Subject: C141 Central Dagger Draw Water Station
Attachments: C141 Central Dagger Draw Water Station Initial.pdf

Mr. Bratcher,

Please find attached the C141 Initial for the below listed location:

**Central Dagger Draw Water Transfer
Section 3, T20S-R24E
2080 FSL & 660 FEL
Eddy County, New Mexico**

Thanks,

Chase Settle
**Environmental Regulatory Agent
Yates Petroleum Corporation
105 S. 4th Street
Artesia, NM 88210
575-748-4171 (Office)
575-703-6537 (Cell)**

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
