

NM OIL CONSERVATION

ARTESIA DISTRICT

NOV 14 2014

Form C-141
Revised October 10, 2003

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

RECEIVED

Release Notification and Corrective Action

NAB1432234636 OXY USA INC. OPERATOR Initial Report Final Report

Name of Company	Oxy Permian Ltd. <u>1101996</u>	Contact	CJ Summers
Address	1017 W. Stanolind Rd, Hobbs, NM	Telephone No.	(575) 397-8216
Facility Name	Sand Dunes 28 Federal #1 SWD Battery	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	
		API No.	30-015-26194

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	28	23S	31E					Eddy

Latitude N 32.27336° Longitude W 103.78031°

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	22 bbls	Volume Recovered	0 bbls
Source of Release	Nipple on discharge header at the west injection pump was off	Date and Hour of Occurrence	10/23/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson-NMOCD, Sol Hughes-BLM		
By Whom?	Kathy Purvis @ BBC International, Inc.	Date and Hour	10/24/2014 @ 8:39 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*


The nipple on the discharge header at the west injection pump was off allowing 22 bbls of produced water to leak onto the ground. No fluids were recovered and the nipple was replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 12' x 100' on location and 5' x 100' off location. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 

Printed Name: Chancey Summers

Title: HES Advisor

E-mail Address: Chancey.Summers@oxy.com

Date: 11-13-14

Phone: (575) 397-8216

Signed By 
Approved by District Supervisor:

Approval Date: 11/18/14

Expiration Date: N/A

Conditions of Approval:

Attached

Remediation per O.C.D. Rules & Guidelines

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: 12/18/14

2RP-2601

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Kathy Purvis <kathy@bbcinternational.com>
Sent: Friday, November 14, 2014 11:57 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; shughes@blm.gov
Cc: C J Summers; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com
Subject: Initial C-141, Sand Dunes 28 Federal #1 SWD Battery
Attachments: Initial C-141, Sand Dunes 28 Federal #1 SWD Battery.pdf

Attached is the initial C-141 for a leak that occurred at the Sand Dunes 28 Federal #1 SWD Battery on 10/23/2014 in Eddy County, NM. Receipt notification via email is greatly appreciated.

Kathy Purvis

BBC International, Inc.
1324 W. Marland
Hobbs, NM 88240
Phone: (575) 397-6388
Fax: (575) 397-0397
Email: kathy@bbcinternational.com

Patterson, Heather, EMNRD

From: Jennifer Gilkey <jgilkey@bbcinternational.com>
Sent: Friday, October 24, 2014 8:39 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; shughes@blm.gov
Cc: CJ Summers; Cliff Brunson ; Ken Swinney; Kathy Purvis ; Jennifer Gilkey
Subject: Sand Dunes 28 Federal #1 SWD Btry

This is to inform you that Oxy Permian Primary NM South had a leak at the Sand Dunes 28 Federal #1 SWD Battery on October 23, 2014. Oxy spilled 22 bbls of produced water due to a discharge header nipple being off on the west injection pump. The preliminary report shows the leak measuring approximately 12' x 100' on location and 5' x 100' off location. No fluids were recovered. The release is located in U/L J, Section 28, T23S, R31E of Eddy County, NM. BBC International will remediate the location at a later date and an initial C-141 will follow. Driving directions: From the intersection of CR29 (Red Rd.) and Hwy 128, go West on Hwy 128 for 3.5 miles to Pure Gold Road (mm14), turn left (South) on Pure gold Road for 0.7 mile, turn left (East) for 0.6 mile to location. API#30-015-26194, GPS coordinates: N 32.27336° W 103.78031°

.....
Jennifer Gilkey

Administrative Manager

BBC International, Inc.

Phone: (575) 397-6388

Fax: (575) 397-0397

E-mail: jgilkey@bbcinternational.com

1324 W. Marland Blvd.

Hobbs, NM 88240
.....