

NOV 14 2014

Form C-141
Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1432352627

OPERATOR

Initial Report Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 th Street	Telephone No. 575-748-1471	
Facility Name Jester SWD #4	Facility Type Production Pad	

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-35217
--------------------------	--------------------------	-------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	12	24S	29E	990	North	1650	West	Eddy

Latitude 32.23657 Longitude 103.94079

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 30 B/PW	Volume Recovered 30 B/PW
Source of Release Valve (inside battery area)	Date and Hour of Occurrence 10/29/2014; AM	Date and Hour of Discovery 10/29/2014; AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOCD II	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 10/30/2014; AM (Email) <i>10/30/14 7:38AM</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A leak in the butterfly valve caused the release. Vacuum truck(s) and roustabout crew were called.

Describe Area Affected and Cleanup Action Taken.*

An approximate area of 80' X 20' within the bermed and lined battery. The release was stopped, the valve was repaired and 100% of the spill was recovered using a vacuum truck (s). **Depth to Ground Water: >100' (approximately 125', per ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0. Based on the battery is lined/bermed and all released produced water recovered, Yates Petroleum Corporation requests closure.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Robert Asher</i>	Approved by Environmental Specialist: <i>Mike Bratcher</i>	
Printed Name: Robert Asher	Approval Date: <i>11/18/14</i>	Expiration Date:
Title: NM Environmental Regulatory Supervisor	Conditions of Approval: <i>FINAL</i>	Attached <input type="checkbox"/>
E-mail Address: boba@yatespetroleum.com	2RP-	
Date: November 14, 2014	Phone: 575-748-4217	

* Attach Additional Sheets If Necessary

2RP-2610

Bratcher, Mike, EMNRD

From: Tanna Adams <TCAdams@yatespetroleum.com>
Sent: Friday, November 14, 2014 11:26 AM
To: Bratcher, Mike, EMNRD
Cc: Patterson, Heather, EMNRD; Bob Asher
Subject: Jester SWD #4
Attachments: Jester SWD #4.pdf

Mr. Bratcher,

Please find attached the signed C141 Initial/Final for the below listed location:

Jester SWD #4
30-015-35217
Section 12, T24S-R29E
990 FNL & 1650 FWL
Eddy County, New Mexico

Thank you,

Tanna Adams
Yates Petroleum Corporation
Environmental Tech
Environmental Department
TCAdams@yatespetroleum.com

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.

Patterson, Heather, EMNRD

From: Bob Asher <BobA@yatespetroleum.com>
Sent: Thursday, October 30, 2014 7:38 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Dade, Randy, EMNRD; jamos@blm.gov; dwhitloc@blm.gov
Cc: Amber Cannon; Chase Settle; Katie Parker; Manuel Gonzalez; Tanna Adams
Subject: Release Notification (Jester SWD #4)

Yates Petroleum Corporation is reporting a release at the following location (10/29/2014; 11:30 AM).

Jester SWD #4
30-015-35217
990' FNL & 1650' FWL
Section 12, T24S-R29E
Eddy County, New Mexico

Released: Approximately 40 B/O & PW mix; Recovered: In progress

Cause of release was unknown at this time. Vacuum truck(s) called and in process of recovering release produced water. The battery is bermed and lined and was contained inside berm. A Form C-141 with full detailed information will be submitted.

Thank you.

Robert Asher
NM Environmental Regulatory Supervisor
Yates Petroleum Corporation
105 S. 4th Street
Artesia, NM 88210
575-748-4217 (Office)
575-365-4021 (Cell)

This message may contain confidential information and is intended for the named recipient only. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited. E-mail transmission cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. If verification is required please request a hard-copy version.
