

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1432550182 OPERATOR Initial Report Final Report

Name of Company Cimarex Energy <i>11621283</i>	Contact Christine Alderman
Address 600 N Marienfeld Ste 600 Midland TX	Telephone No. 432-853-7059
Facility Name Vega 9 Federal #2	Facility Type production
Surface Owner	Mineral Owner
API No. 30-015-36328	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	09	17S	30E	330	N	810	W	Eddy

Latitude 32.85548 Longitude -103.98298

NATURE OF RELEASE

Type of Release oil and produced water	Volume of Release 4 bbls oil, 10 bbls PW	Volume Recovered 0 bbls oil, 0 bbls PW
Source of Release flowline	Date and Hour of Occurrence 11/18/14	Date and Hour of Discovery 11/18/14 4:30 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/Sol Hughes	
By Whom? Gloria Garza	Date and Hour 11/20/14 3:18pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

NM OIL CONSERVATION
ARTESIA DISTRICT
NOV 21 2014

Describe Cause of Problem and Remedial Action Taken.*

2 7/8" steel flowline from well to battery developed a leak due to corrosion.

RECEIVED

Describe Area Affected and Cleanup Action Taken.*

Pasture area approx. 60' x 12', 6' x 6', and 10' x 5'. Talon has been contacted to assess and develop work plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: *Christine Alderman*

Printed Name: Christine Alderman

Approved by Environmental Specialist: *[Signature]*

Title: ESH Supervisor

Approval Date: *11/21/14*

Expiration Date: *NA*

E-mail Address: calderman@cimarex.com

Conditions of Approval:

Attached

Date: Phone: 432-853-7059

Remediation per O.C.D. Rules & Guidelines

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: *12/21/14*

2RP-2619

* Attach Additional Sheets If Necessary

Patterson, Heather, EMNRD

From: Christine Alderman <calderman@cimarex.com>
Sent: Friday, November 21, 2014 12:49 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; shughes@blm.gov
Cc: Gloria Garza; David Adkins (dadkins@talonlpe.com)
Subject: C-141 - Vega 9 Fed Battery (fire) and Vega 9 Fed #2 (spill)
Attachments: 20141121123736487.pdf; 20141121122700538.pdf

Categories: printed

All,

Please find attached C-141's for the above mentioned leases.

Please let me know if you need anything else. Thank you!

Christine Alderman

ESH Supervisor – Permian Basin

Mobile: 432-853-7059

Office: 432-620-1982

