


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company : Oxy Permian LTD (192463)	Contact : Chris Jones
Address : 1502 W. Commerce, Carlsbad, NM 88220	Telephone No. : 575-628-4121
Facility Name : North Burton Flats Battery	Facility Type: Central Tank Battery

Surface Owner : Federal	Mineral Owner	API#: 30-015-33283 2RP-1649
-------------------------	---------------	-----------------------------

LOCATION OF RELEASE

Unit Letter D	Section 23	Township 20S	Range 28E	Feet from the	North/South Line	Feet from the	East/West Line	County: Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	--------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release : Produced Fluids	Volume of Release : 40 bbls	Volume Recovered: 10 bbls
Source of Release : Heater Treater	Date and Hour of Occurrence: 3/17/2013 7:00 am	Date and Hour of Discovery: 3/17/2013 7:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD/Mike Bratcher & BLM/Jim Amos	
By Whom: Jonathan Haver 575-706-9249	Date and Hour : 3/18/2013 2:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* A flange leaked on the heater treater causing a release of 40 barrels of produced fluids. The heater treater was taken out of service, repaired and put back into production. A vac truck was immediately called to the location and recovered 10 barrels of produced fluids. The area impacted measured approximately 10'x60'

Describe Area Affected and Cleanup Action Taken.* Talon/LPE was contracted for the correction of this release. The impacted areas from sample location S-2 and S-5 of this release was excavated to a depth of 2-feet deep. The remainder of the impacted area was excavated to a depth of 1-foot deep, excluding the area identified as S-4. The impacted soil was transported to Lea Land, LLC, an approved NMOCD disposal facility. The excavation was backfilled to grade using new material and was contoured to match the surrounding location.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Chris Jones	Approved by District Supervisor:	
Title: HES Specialist	Approval Date: 8/4/14	Expiration Date: NA
E-mail Address: Christopher Jones@oxy.com	Conditions of Approval: <i>Final</i>	Attached <input type="checkbox"/>
Date: 7/2/2013 Phone: 575-628-4121		

* Attach Additional Sheets If Necessary

2RP-1649