

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION**

ARTESIA DISTRICT

Form C-141  
Revised August 8, 2011

DEC 09 2014

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

*NAB1434450914*

**OPERATOR**

Initial Report  Final Report

Name of Company <b>Devon Energy</b>	<i>U137</i>	Contact <b>Tom Pettyjohn</b>
Address <b>PO Box 250 Artesia, NM 88211</b>		Telephone No. <b>575-748-9922</b>
Facility Name <b>Daisy Duke 31-3H</b>		Facility Type <b>Tank battery</b>

Surface Owner	State	Mineral Owner	State	API No. <b>3001542224</b>
---------------	-------	---------------	-------	---------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	31	22S	26E	1980	South	175	East	Eddy

Latitude: 32.346 Longitude: 104.324

**NATURE OF RELEASE**

Type of Release <del>Clean Brine Water</del> <i>PW</i>	Volume of Release 5-7 BBL	Volume Recovered 0
Source of Release Heater Treater	Date and Hour of Occurrence 12/4/14 9:30 am	Date and Hour of Discovery 12/4/14 9:30 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Crossfire was changing a valve around on a heater treater and released 5-7 bbl of clean brine water. Remedial action taken will be to clean up the soil.

Describe Area Affected and Cleanup Action Taken.\*

The area affected was the lease pad and the water was sucked up.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jessica Sanchez</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Jessica Sanchez</b>	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: <b>Field Admin Support</b>	Approval Date: <i>12/10/14</i>	Expiration Date: <i>NA</i>
E-mail Address: <b>Jessica.Sanchez@dvn.com</b>	Conditions of Approval:	
Date: <b>12.5.14</b> Phone: <b>575-746-5594</b>	<b>Remediation per O.C.D. Rules &amp; Guidelines</b> <b>SUBMIT REMEDIATION PROPOSAL NO</b> <b>LATER THAN: <u>1/10/15</u></b>	

Attached

\* Attach Additional Sheets If Necessary

*2RD-2649*

## Patterson, Heather, EMNRD

---

**From:** Oberding, Tomas, EMNRD  
**Sent:** Tuesday, December 09, 2014 9:17 AM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD  
**Cc:** Sanchez, Jessica  
**Subject:** FW: C-141 Daisy Duke 31-3H 12/8/14  
**Attachments:** C-141 Daisy Duke 31-3H.doc

Hi Jessica,  
This is Eddy county, belongs to Artesia. They will take care of you regarding the spill.  
(hint XX-015-XXXXX, usually belongs to them XX-025-YYYYYY is mine in district 1, 95% of the time ☺).  
Cheers all  
-Doc

Tomáš 'Doc' Oberding, PhD  
Senior Environmental Specialist – New Mexico Oil Conservation Division  
Energy, Minerals and Natural Resources Department  
1625 N. French Dr.  
Hobbs, NM 88240  
(O): (575) 393-6161 ext 111  
(C): 575-370-3180  
(F): (575) 393-0720  
E-Mail: [tomas.oberding@state.nm.us](mailto:tomas.oberding@state.nm.us)  
Website: <http://www.emnrd.state.nm.us/ocd/>

---

**From:** Sanchez, Jessica [<mailto:Jessica.Sanchez@dvn.com>]  
**Sent:** Monday, December 08, 2014 8:30 AM  
**To:** Oberding, Tomas, EMNRD  
**Subject:** C-141 Daisy Duke 31-3H 12/8/14

Tomas,

Attached is the C-141 form for the Daisy Duke 31-3H. If there is anything else you need from us please let us know.  
Thank you and have a wonderful week!

Thank you,

*Jessica Sanchez*  
Field Admin Support - Construction

Devon Energy Corporation  
6488 Seven Rivers Hwy  
Artesia, NM 88210  
575-746-5594  
[Jessica.Sanchez@dvn.com](mailto:Jessica.Sanchez@dvn.com)



Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.