

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT Form C-141
Revised August 8, 2011
DEC 18 2014
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1435732150 OPERATOR Initial Report Final Report

Name of Company Devon Energy Production <u>0137</u>	Contact Production Foreman; Joah Weidemann
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 575-513-1528
Facility Name Snapping 2 State 6H	Facility Type Oil

Surface Owner: State	Mineral Owner: State	API No. 30-015-39162
----------------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter O	Section 2	Township 26S	Range 31E	Feet from the 330	North/South Line South	Feet from the 2260	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude: 32.0657885N Longitude: 103.7475812W

NATURE OF RELEASE

Type of Release Spill	Volume of Release 30BBLS	Volume Recovered 25BBLS
Source of Release pop off on the 3 phase separator	Date and Hour of Occurrence 11-24-2014 5:00 AM	Date and Hour of Discovery 11-24-2014 5:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos; BLM Heather Patterson; OCD	
By Whom? Lynn Smith; Assistant Production Foreman	Date and Hour 11-25-2014 @ 8:00 AM <u>8:12AM</u>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
The pop off valve on the 3 phase separator released 30BBLS of fluid on location due to a malfunction of the motor valve on the flare line. The fluid could not dump because the supply gas to the dump valve was frozen. The well was immediately shut in and the motor valve has been repaired.

Describe Area Affected and Cleanup Action Taken.*
On the north central side of the location 30BBLS of oil was released affecting an area approximately 195' x 165'. The spill remained on location. 25BBLS were recovered via vacuum truck. The affected equipment has been pressure washed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Sandra Farley</u>	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Sandra Farley	Approved by Environmental Specialist: <u>[Signature]</u>	
Title: Field Admin Support	Approval Date: <u>12/22/14</u>	Expiration Date: <u>NA</u>
E-mail Address: Sandy.Farley@dvn.com	Conditions of Approval:	
Date: 11-26-2014 Phone: 575.746.5587	<input checked="" type="checkbox"/> Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> Attached	

* Attach Additional Sheets If Necessary

REMIT REMEDIATION PROPOSAL NO
LATER THAN: 1/22/15

2RP-2686

ENVIRONMENTAL RELEASE NOTIFICATION

Call-In Sheet

Date: 11/25/14

Notice received by: HP

Devon 575-234-0222
Name of Company/Phone #

Snapping Turtle ...
Facility Name

3U-015-39162 ?
API # Sec. Township Range Date of Occurrence

? ? 30 bbl 25 bbl
Date/Hour of Discovery Type of Release Volume of Release Volume Recovered

Briefly Describe Cause of Problem and action taken: message left on phone

Lina Smith 11/25/14 8:12 am
Notice given by: Name/ Company Date/Hour Immediate Notice given

Date C-141 received: _____ 2RP- _____

FLARE NOTIFICATION

Call-In Sheet

Date: _____

Notice received by: _____

Name of Company/Phone #

Facility Name

Date of Occurrence Date/Hour of Flare Type of Release

Flared MCF Volume Volume Recovered

Briefly Describe Cause of Problem and action taken: _____

Notice given by: Name/ Company Date/Hour Immediate Notice given

Date C-141 received: _____ 2RP- _____