

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

FAB1501227053
NAB1501227217

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Enterprise Field Services LLC	Contact Dina Babinski
Address PO Box 4324, Houston TX 77252	Telephone No. 210-528-3824
Facility Name Pipeline ROW, 1003 Gathering Lateral	Facility Type Gas Gathering Pipeline

Surface Owner Private Owner	Mineral Owner NA - Pipeline	API No. NA
------------------------------------	------------------------------------	-------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	36	24S	28E	591	North	427	East	Eddy

Latitude N 32.17956 Longitude W -104.04650

NATURE OF RELEASE

Type of Release Liquid Overspray	Volume of Release 8 BBL	Volume Recovered NA
Source of Release Pipeline Relief Valve	Date and Hour of Occurrence 12/19/2014 @ 7:00 MST	Date and Hour of Discovery 12/20/2014 @ 12:20 MST
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

NM OIL CONSERVATION
ARTESIA DISTRICT
JAN 09 2015
RECEIVED

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

The pipeline relief valve activated and sprayed liquid over the surrounding area. No pipeline or valve damage occurred, so no repair activities were necessary.

Describe Area Affected and Cleanup Action Taken.*

Oversprayed areas will be treated with microblaze or other in-situ techniques. Excavation will be performed on areas where liquids penetrated the ground. Soil sampling will be performed to confirm that remediation actions meet NMOCD remediation levels, and will follow-up with a final C-141 form.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Ivan Zirbes	Approved by	Signed By 
Title: Sr. Director, Environmental	Approval Date: 11/21/15	Expiration Date: N/A
E-mail Address: snolan@eprod.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: 1/5/15 Phone: 713-381-6595	SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 1/21/15	

* Attach Additional Sheets If Necessary

289-2721



ENTERPRISE PRODUCTS PARTNERS L.P.
ENTERPRISE PRODUCTS HOLDINGS LLC
(General Partner)

ENTERPRISE PRODUCTS OPERATING LLC

January 5, 2015

NM OIL CONSERVATION
ARTESIA DISTRICT
JAN 09 2015

7014 2120 0001 5336 8667
Return Receipt Requested

RECEIVED

Mr. Mike Bratcher
New Mexico Oil Conservation Division
District 2 Office
811 South First Street
Artesia, New Mexico 88210

**RE: Form C-141 Report for Enterprise Field Services LLC
Releases on Carlsbad Area Gathering Lines**

Dear Mr. Bratcher:

Enclosed, please find the required C-141 Form for the pipeline liquid release on our 1003 Line in Eddy County on December 19, 2014. The pipeline relief valve activated and sprayed liquid over the surrounding area. Remediation activities are currently being performed, and a final C-141 form will be submitted when soil sampling results demonstrate that cleanup is satisfactory. This report is sent pursuant to NMAC 19.15.29 requirements for minor releases.

If you have any questions or need additional information, please contact Dina Babinski, our area Environmental Supervisor by phone at 210-528-3824 or via email at djbabinski@eprod.com or Jon Fields, Director of Field Environmental at 713-318-6684.

Regards,

Ivan Zirbes
Sr. Director, Environmental

/bjm
Attachment