

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION**  
ARTESIA DISTRICT

JAN 13 2015

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**RECEIVED**

**Release Notification and Corrective Action**

*NAB1501441507*

**OPERATOR**

Initial Report  Final Report

Name of Company: <b>Devon Energy Production Co LP (6137)</b>	Contact: <b>Brian Kuh</b>
Address: <b>PO Box 250 Artesia, NM 88211</b>	Telephone No. <b>575- 616-1540</b>
Facility Name: <b>Cotton Draw 11 Federal #2H</b>	Facility Type: <b>Well location</b>

Surface Owner: <b>Federal</b>	Mineral Owner: <b>Federal</b>	API No. <b>30-015-39375</b>
-------------------------------	-------------------------------	-----------------------------

*AKA Cotton Draw Unit 163 H*

**LOCATION OF RELEASE**

Unit Letter <b>C</b>	Section <b>11</b>	Township <b>25S</b>	Range <b>31E</b>	Feet from the <b>330</b>	North/South Line <b>North</b>	Feet from the <b>1980</b>	East/West Line <b>West</b>	County <b>Eddy</b>
-------------------------	----------------------	------------------------	---------------------	-----------------------------	----------------------------------	------------------------------	-------------------------------	-----------------------

Latitude: \_\_\_ Longitude: *32.151232*  
*103.750816*

**NATURE OF RELEASE**

Type of Release: <b>Produced water</b>	Volume of Release: <b>15 bbls</b>	Volume Recovered: <b>15 bbl</b>
Source of Release: <b>Bosque produced water filtering pod</b>	Date and Hour of Occurrence <b>01/12/2015, approx. 6:25 A.M.</b>	Date and Hour of Discovery <b>01/12/2015, approx. 6:25 A.M.</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>OCD-Mike Bratcher                      BLM-Jim Amos</b>	
By Whom? <b>Brian Kuh, Foreman</b>	Date and Hour: <b>01/12/2015;    OCD: 2:41 P.M.    BLM: 2:44 P.M.</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
On the Cotton Draw 11 Fed 2H, a Bosque employee was changing the filter socks in the dual filter pod when the hose connecting to the KC nipple directly underneath the filter pot disconnected causing the release of approximately 15 barrels of produced water. The hose clamp that holds the hose in place broke causing the pressure of the water to disconnect the hose. The produced water overflowed it's containment (20 ft x 20 ft x 8 in) due to one corner of the containment being lower than the rest, which was caused by an unlevelled surface. Approximately 10 barrels of produced water escaped the containment and on to the pad while another 5 barrels stayed in the containment. The produced water did not leave the pad. Cleanup at the location was started shortly after the release and was completed that day.

Describe Area Affected and Cleanup Action Taken.\*  
A vacuum truck, skid steer, backhoe, and dump truck were all used to clean up the entire spill.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Denise Menoud</b>	Signed By <i>Mike Bratcher</i>	
Title: <b>Field Admin Support</b>	Approval Date: <i>1/14/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: <b>Denise.Menoud@dvn.com</b>	Conditions of Approval: <b>FINAL</b>	Attached <input type="checkbox"/>
Date: <b>01/13/2015</b> Phone: <b>575-746-5544</b>		

\* Attach Additional Sheets If Necessary

*2RP-2736*

**Bratcher, Mike, EMNRD**

---

**From:** Menoud, Denise <Denise.Menoud@dvn.com>  
**Sent:** Tuesday, January 13, 2015 10:51 AM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Menoud, Denise  
**Subject:** C141 attached - Cotton Draw 11 Fed 2H  
**Attachments:** C-141 Bosque 1\_12\_15.doc

Please send confirmation # for the attached C141. Thank you.

***Denise Menoud***

Admin Field Support 4 / Completions  
Devon Energy Production Co. LP/Artesia NM  
[Denise.Menoud@dvn.com](mailto:Denise.Menoud@dvn.com)  
575-746-5544

Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.