

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**  
AUG 30 2012  
NMOCD ARTESIA

Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	BOPCO, LP	Contact	Tony Savoie
Address	522 W. Mermod, Suite 704 Carlsbad, NM 88220	Telephone No.	(432) 556-8730
Facility Name	James Ranch Unit #112-H Pumping Well	Facility Type	E & P

Surface Owner	State of N.M.	Mineral Owner:	State of N.M.	Lease No.	NM 02953-C
---------------	---------------	----------------	---------------	-----------	------------

**LOCATION OF RELEASE**

30-015-36722

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	36	22S	30E					Eddy

Latitude N. 32.34270 Longitude W 103.82626

**NATURE OF RELEASE**


Type of Release	Crude oil and produced water	Volume of Release	15 bbls crude oil and 15 bbls produced water	Volume Recovered:	10 bbls total fluid
Source of Release:	Pump Jack Well Head	Date and Hour of Occurrence	4/30/12 Time unknown	Date and Hour of Discovery	4/30/12 9:00 a.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	NMOCD Emergency #104		
By Whom?	Tony Savoie	Date and Hour:	4/30/12 2:49 p.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* The well pressured up and blew out the stuffing box packing. The packing was replaced and the pressure problem was corrected.

Describe Area Affected and Cleanup Action Taken.\* An area covering approximately 1800 sq. ft. on the caliche well pad was affected by the release. The release was remediated according to NMOCD guidelines for spill remediation. Please see the attached Remediation Summary and Site Closure Request, dated May 2012, for details of remediation activities and analytical results from confirmation soil samples.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases, which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: Tony Savoie	Approved by District Supervisor:		
Title: Waste Mgmt. & Remediation Specialist	Approval Date: 8/16/12	Expiration Date:	N/A
E-mail Address: tasavoie@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: 8/30/12 Phone: (432) 556-8730	Final		

2RP-1141